



GTO / 4-

Index

Antenna Parts	229	Gas Tank Sending Units	247	Rear Control Arms	257
Armrest Bases	256	Gas Tank Straps	246	Rear Interior Quarter Ashtrays	254
Ashtrays, Rear Quarter Interior	254	Glovebox Latches	253	Rear Interior Quarter Trim and Ashtrays	254
Battery Trays and Hardware	232	Grille and Front Trim Parts	227	Rear Interior Quarter Trim Panels	254
Bucket Seat Mounting Bracket Sets	239	Grille Emblems	248	Rear Spoiler Pads	242
Carpet Guards	233	Hardtop Roofrail Weatherstrips	250	Rear Wheelhouses	241
Carpet Sill Plates	237	Headlamp Bezels	227	Rocker Panels	237
Chrome Bumpers	227	Headlamp Switches and Parts	252	Roofrail Weatherstrips	250
Cigarette Lighter Parts	252	Headliner and Coat Hook Parts	253	Rubber Bumper Kits	249
Clutch Linkage Kits	232	Heater / A/C Parts	252	Seat Belt Mounting Bolts and Parts	256
Clutch Linkage Parts	232	Hood Adjustment Bumpers	230	Seat Parts and Trim	255
Coat Hook Parts	253	Hood Hinge Springs	230	Shift Boots and Retainers	240
Convertible Pillar Post Weatherstrips	250	Hood Insulation Pads and Clips	230	Shifters and Shift Knobs	254
Convertible Pinch Weld Molding Clips	242	Hood Latches	230	Spare Tire Parts	244
Convertible Top Boot Clips	242	Hood to Cowl Seals	248, 249	Speedometer Cables and Grommets	233
Convertible Top Latch Parts	237	Inner Fenders	230	Steering Column Parts	253
Coolant Overflow Jar Caps	232	Inside Door Handles	236	Steering Column Seals and Carpet Guards	233
Dash Pads	251	Inside Rear View Mirrors	256	Steering Wheel Parts	253
Deck Filler Panels	243	Inside Rear View Mirrors and Brackets	256	Sunvisor Supports and Brackets	256
Disc Brake Backing Plates	257	Instrument Cluster Applique Kits	251	Tail Panels	247
Dome Lamp Lenses and Bases	253	Instrument Cluster Inserts	251	Toe Boards and Torque Boxes	233
Door Glass Guides	236	Kick Panels	251	Trunk Divider Boards and Insulation Kits	254
Door Hinge Rebuild Kits	235	License Plate Brackets	227	Trunk Floor Drop-Offs	244
Door Jamb Stickers	248	License Plate Lamps	227	Trunk Floors	243
Door Jamb Windlace	251	Lug Nuts	256	Trunk Latches	242
Door Latch Assemblies	236	M/T Floor Shift "Humps"	239	Trunk Lids	242
Door Latch Remotes	236	Mirrors, Inside Rear View	256	Trunk Weatherstrips	250
Door Lock Knobs & Ferrules	236	Oil Pans	231	Valve Cover Bolt Sets	231
Door Panel Hardware	251	Outside Door Handles	236	Vent Knobs	251
Door Strikers	241	Outside Rear View Mirrors	235	Vent Knobs and Cables	251
Door Weatherstrips	250	Package Trays and Insulation Kits	254	Vent Knobs and Cables and Kick Panels	251
Drip Rail Molding Sets	237	Park Brake Parts	240	Vent Window Frames	235
Emblems	248	Pedal Pads and Parts	254	Vent Window Handles	235
Fan Shrouds	232	Pillar Post Weatherstrips	250	Vent Window Weatherstrips	249
Fender Emblems	248	Quarter Glass Sash Chrome	242	Weatherstrip Kits	248, 249
Firewall Insulation Pads	233	Quarter Glass Weatherstrips	250	Weatherstrips	248
Floor Pan Braces	239	Quarter Panel "C" and Trunk Lid Moldings	242	Wheel Center Caps	257
Floor Pan Brackets	239	Quarter Panel Emblems	248	Wheel Trim Rings	257
Floor Pan Plugs	239	Radiator Caps	232	Window Channel Kits	249
Floor Pans	238	Radiator Support Bushings	231	Windowfelt Kits	249
Floor Shift "Humps"	239	Radiator Supports	230	Windshield Reveal Molding Sets	237
Floor Shift Boots and Retainers	240	Radiator Support Seals	232	Windshield Sealing Kits	250
Front Bumper Emblems	248	Radio Knobs and Nuts	252	Windshield Wiper Switches and Parts	252
Front Control Arms	257	Rear Axle Cover	257		
Gas Caps	246	Rear Axle Covers	257		
Gas Tanks	245	Rear Coil Spring Insulators	257		

-4-2 / GS



Buick/Olds/PONTIAC

"A Bodies", such as the Buick Special / Skylark / GS, Oldsmobile F-85 / Cutlass / 442, and Pontiac Tempest / LeMans / GTO, are worshiped by their fans, and are famous for their winning history at the track and on the streets of America. Until recently only a few parts were available for these "other" A-Bodies. But the restoration professionals at Goodmark are hard at work developing more and more premium parts for these popular muscle cars. Review the following pages carefully, and keep an eye on Goodmark's fine website for the latest announcements in newly available parts for Buick, Oldsmobile, and Pontiac A-Bodies. Or, call your representative at Goodmark today!



BUMPERS AND GRILLES

These Premium Quality Bumpers are new, die-stamped, high quality steel, triple plated, and fit perfectly. The show-quality plating process of copper/ nickel/ chrome meets original factory standards. Get a set of these excellent bumpers for your car, and show them off to the world.

Chrome Bumpers

New chrome bumpers for popular models. These bumpers are designed to replace dull or corroded factory units. Premium bumpers are chromed in the USA for the ultimate in quality!



66-67 Pontiac Front - Premium Quality - USA Chrome
..... 4331-000-66A \$409.95 ea



68-69 Pontiac Rear (except Wagon) - Premium Quality - USA Chrome
'68 4332-800-68A \$399.95 ea
'69 4332-800-69A \$399.95 ea



71-72 Oldsmobile Front 4533-000-71 \$279.95 ea
Premium Quality - USA Chrome 4533-000-711A \$405.95 ea



70 Oldsmobile Rear (except Wagon)
(w/o exhaust tip cuts) 4533-800-701 \$279.95 ea
Premium Quality - USA Chrome 4533-800-701A \$399.95 ea
(w/ exhaust tip cuts) 4533-800-702 \$279.95 ea
Premium Quality - USA Chrome 4533-800-702A \$399.95 ea



71-72 Oldsmobile Rear (except Wagon) (without bumper guard holes)
(w/o exhaust tip cuts) 4533-800-711 \$279.95 ea
Premium Quality - USA Chrome 4533-800-711A \$399.95 ea
(w/ exhaust tip cuts) 4533-800-712 \$279.95 ea
Premium Quality - USA Chrome 4533-800-712A \$399.95 ea

Chrome Bumpers

71-72 Oldsmobile Rear (except Wagon) (with bumper guard holes)
(w/o exhaust tip cuts) 4533-800-713 \$279.95 ea
(w/ exhaust tip cuts) 4533-800-714 \$279.95 ea



78-83 Wagon Rear (with impact strip holes) 4085-800-782 \$249.95 ea



License Plate Brackets

Chromed and painted molded plastic panels that holds the rear license tag.

78-87 License Tag Pocket, Wagon 4085-885-78 \$98.95 ea



License Plate Lamps

Lenses and gaskets for the rear license lamp assembly.

64-72 Lens Only 4011-887-66 \$10.95 ea

64-72 Lens Gasket Only 4011-887-662 \$7.65 ea

Grille and Front Trim Parts

We all know that flawed trim can spoil the looks of any car. A bar or molding that is missing or bent, a ding, a crack, or blemish will mess up the "detailed" look of the whole front end. Get a brand new Goodmark® grille and show the world a "new face" on your car. These quality grilles are made from molded plastic just like the originals. Looking good!



65 Pontiac Headlamp Bezel Seals, pair 4330-060-652P \$10.95 pr



66-67 Pontiac Headlamp Bezels, pair 4331-060-66P \$219.95 pr

Bezel Hardware Kit 4331-060-66S \$10.95 kit



69 GTO Grilles, Left / Right Pair (includes chrome moldings molded in) 4332-050-691P \$219.95 pr

NOTE: Paint inserts black for Judge models.



GTO / 4-

FRONT LAMPS

Being able to light up the road and see ahead driving at night is an important safety factor. Old lenses can be dull and fogged, and in some cases cracked from age or collision damage. We offer new reproduction lamp lenses and gaskets to make replacement and restoration easy.

Headlamp Capsules

Replacement style headlamp capsules for popular models. Each capsule contains a sealed beam unit, mounting ring, and retaining ring, ready to install.

(photo not available)

71-77 All with 2 round headlamps (use 2)
(sealed beam only) 4012-066-71 \$16.45 ea



76-87 All with 4 square headlamps
Outer Headlamp (std.), LH / RH . . . 4145-061-811L / R . . \$54.95 ea
Inner Headlamp (std.), LH / RH . . . 4145-061-812L / R . . \$54.95 ea
Outer Headlamp (Halogen), L / R . . . 4145-061-814L / R . . \$54.95 ea
Inner Headlamp (Halogen), LH / RH 4145-061-813L / R . . \$65.95 ea



78-80 All with 2 square headlamps
Standard (use 2) 4313-061-77 \$49.45 ea
Halogen (use 2) 4035-061-80 \$54.95 ea

Headlamp Retaining Rings

New correct headlamp retaining rings and screws used on most models. Use as required. These hold the sealed beam to the mounting ring.



64-66 All (set of 4) 4041-062-58S \$21.95 set
68-72 Special / Skylark / GS (set of 4) 4032-062-68S \$21.95 set
71-72 Grand Prix (Use 2) 4021-062-71 \$10.95 ea
73-77 All with round headlamps (use 2) 4144-062-73 \$109.95 ea
64-72 Screw Kit (6 Pieces) (use 2) 4141-062-581S \$10.95 kit

Headlamp Mounting Rings

EDP coated steel ring that holds the headlamp sealed beam.



65-67 Pontiac (set of 4) 4031-063-67S \$98.95 set
68-70 Pontiac (set of 4) 4332-063-68S \$109.95 set
73-77 All with 2 round headlamps (use 2) 4144-063-73 \$65.95 ea

Headlamp Adjusting Kits

All the correct screws, nuts, and springs you need to replace all your headlamp adjusters. Individual components are sold in bulk also. Order as required.



64-67 Olds / Buick Adjusting Kit (20 pieces)
. 4031-069-67S \$21.95 kit
68-70 GTO (with Endura Bumper), '69 Tempest / LeMans
Adjusting Kit (20 pieces) 4332-069-682S \$43.95 kit



64-68 Pontiac (without Endura Bumper), '70 Tempest / LeMans, '69-70
Grand Prix Screw and Nut Assembly,
box of 25 HWB2101 \$16.45 box
68-70 GTO (with Endura Bumper), '69 Tempest / LeMans, '71-75 Pontiac
Screw and Nut Assembly, box of 25 HWB2138 \$27.45 box
76-77 Pontiac Screw and Nut Assembly, box of 25
. HWB2108 \$14.25 box
76-77 Olds, '77 Buick 2-Door Screw and Nut Assembly,
box of 25 HWB2117 \$25.25 box
78-88 Screw and Nut Assembly, box of 25 . . HWB2118 \$14.25 box



64-68 Pontiac, '70 Tempest / LeMans, '69-70 Grand Prix
Screw, box of 50 HWB2150 \$10.95 box
Nut, box of 50 HWB2184 \$14.25 box
64-72 Olds, '64-67 Buick
Screw, box of 25 HWB2106 \$10.95 box
Nut, box of 50 HWB2184 \$14.25 box
73-75 Olds, '75 Buick Screw HW2165 \$4.35 ea



70 Tempest / LeMans, '69-70 Grand Prix
Spring, box of 25 HWB2147 \$14.25 box
Spring Retainer, box of 50 HWB2148 \$10.95 box
71 Pontiac Spring, box of 25 HWB2140 \$16.45 box
72-77 Pontiac (except '75 Grand LeMans)
Spring, box of 25 HWB2135 \$14.25 box
81 Pontiac Spring, box of 25 HWB2142 \$30.75 box



73-75 Olds Spring, box of 25 HWB2163 \$32.95 box
76-81 Olds Spring, box of 25 HWB2166 \$16.45 box
70-72 Buick Spring, box of 25 HWB2162 \$16.45 box
73-75 Century, '76-77 Buick 4-Door Spring,
box of 25 HWB2168 \$27.45 box
80-81 Regal Spring, box of 25 HWB2171 \$27.45 box

-4-2 / GS



Park Lamp Gaskets

New sponge gaskets that keep the lens sealed against the housing. Sold in matched pairs.



- 64-67 Pontiac (except '66-67 GTO) Gaskets, Pair 4330-072-64P \$9.85 pr
- 66-67 GTO Gaskets, Pair 4331-072-662P \$9.85 pr
- 68 Pontiac "A" Gaskets, Pair 4320-072-68P \$9.85 pr
- 69-70 GTO Gaskets, Pair 4332-072-692P \$9.85 pr
- 70 Tempest / LeMans Gaskets, Pair 4333-072-701P \$7.65 pr
- 69-70 Olds "A" Gaskets, Pair 4532-072-69P \$7.65 pr
- 71-72 Olds "A" Gaskets, Pair 4020-072-69P \$9.85 pr

FRONT END SHEETMETAL



Header Panels

EDP coated panels that fill between the hood and grille.



- 66 Pontiac "A" Header Panel 4331-030-66 \$179.95 ea
- 67 Pontiac "A" Header Panel 4331-030-67 \$129.95 ea



- 71-72 Oldsmobile "A" Stone Shield 4533-020-71 \$186.95 ea
- 84-87 Regal Coupe Header Panel 4462-030-84 \$139.95 ea

Front Fenders

You're going to love the way these beautiful brand new steel fenders will fit and look on your Cutlass. Just like original factory fenders with all braces, holes, and threads in place, these fenders are a much better choice than trying to deal with old fender rust, dents, paint, and body filler. These are the best quality on the market, and all fenders are shipped via Truck Freight.



- 68-69 Pontiac, Left / Right (except Grand Prix) 4332-100-68L / R .. \$299.95 ea
- 70-72 Oldsmobile, Left / Right 4533-100-70L / R .. \$399.95 ea



Lower Rear Fender Patches

EDP coated lower rear patches repair rust between the front wheel opening and the door. Best quality on the market!

- 68-69 Pontiac "A", 12" H x 14" W, Left / Right 4332-190-68L / R ... \$43.95 ea



Antenna Parts

Gasket for the mast, and grommet for the lead through the cowl.

- 65-69 all Fender Mount Antenna Gasket 4020-920-675 \$6.55 ea
- Cowl Grommet 4030-374-642 \$6.55 ea

Get new inner fenders!

With all the abuse that Inner Front Fenders have to take, it should be no surprise that they look so bad when you remove them from your car. The top areas usually look okay, up near the seam between the hood line and the outer fender. But it can be a real shocker when you disassemble the front sheet metal, and survey the rust and damage. Batteries leak acid on the Inner Front Fenders, while tires throw up rocks, water, snow, ice, salt, sand, and gravel at tremendous velocities. People often drill extra holes to mount accessories, and even Father Time seems to take a toll on those poor Inner Front Fenders. At Goodmark Industries we have learned to respect inner fenders, as we know how important they are to having proper fitting front sheet metal. And, they show up prominently every time you open your hood. Go ahead, order two new Front Inner Fenders with your new outer front fenders. You'll love the way they look!



GTO / 4-

Inner Fender Wire Straps

New plastic straps that retain wiring to the inner fender on Oldsmobile models. Sold by the box.

70-77 Oldsmobile, box of 50HWB2418\$8.75 box



Inner Fenders

EDP coated steel panels form the inner skirt for the front fenders. Usually rusted from leaking batteries or destroyed from road debris kicked up from the front wheels.

64-67 Pontiac, Left / Right4330-350-64L / R... \$186.95 ea

68-69 Pontiac, Left / Right4332-350-68L / R... \$186.95 ea



Inner Fender Splash Shields

Heavy rubber splash shields with staples are crucial to keeping your engine compartment clean from road spray kicked up from the tires. Be sure to replace these with your new inner fenders.

64-66 Pontiac Upper, pair4330-351-641P\$10.95 pr

64-67 Pontiac Front, pair4330-351-642P\$10.95 pr

Pontiac Rear, pair4330-351-643P\$10.95 pr

67-70 Pontiac Upper, pair4331-351-67S\$10.95 pr

68-72 Pontiac Rear, pair4332-351-68S\$10.95 pr



64-65 Oldsmobile, 4-piece set4530-351-64S\$21.95 set

66-67 Oldsmobile, 4-piece set4531-351-66S\$21.95 set

68-72 Oldsmobile, pair4532-351-68S\$16.45 pr

68-72 Buick, pair4432-351-68P\$16.45 pr

Hood Insulation Pads and Clips

New jute insulation and plastic clips used to hold the insulation pad to the hood. Clips sold by the box, use as required.

68-70 Oldsmobile Hood Pad (exc. '70 OAI) ...4532-202-68S\$32.95 ea

68-72 Buick Hood Pad Set4432-202-68S\$16.45 set

68-70 Oldsmobile Clips, box of 25HWB2402\$14.25 box

71-88 All (exc. '71-72 Buick) Clips, box of 25HWB2401\$6.55 box



Hood Scoop Ornaments

Die cast and painted ornaments for use with popular hoods. Sold as a set for one car.

(photos not available)

65-67 GTO (without Ram Air)4330-255-65\$54.95 ea

68-70 GTO (without Ram Air) (pair)4332-255-68S\$87.95 pr

Hood Adjustment Bumpers

Complete set of the bolts and rubber caps used for the hood adjusters at the front of the hood. Rubber caps are also sold separately. See Rubber Bumper Kits for Hood to Fender Bumpers not found here.



64-65 Pontiac, '64-67 Buick / Oldsmobile

Hood Adjustment Bolts, pair4330-205-64P\$21.95 pr

66-72 Pontiac Rubber Caps, Pair4331-205-661P\$10.95 pr

73-77 Pontiac Rubber Caps, Pair4010-205-62P\$4.35 pr

73-77 Pontiac Hood Adjuster (use 2)4012-205-73\$5.45 ea

68-72 Olds / Buick Hood Adjuster (use 2)4532-205-68\$2.15 ea

73-77 Olds / Buick Hood Adjuster (use 2)4534-205-73\$2.15 ea

Hood Hinges

New (not rebuilt) hinges for the hoods on popular models. Be sure to order new springs if available.



64-67 Pontiac / Oldsmobile, Left / Right4010-210-63L / R... \$43.95 ea

68-72 Pontiac, Left / Right4332-210-68L / R... \$43.95 ea



78-88 Hinge Screw Grommets, box of 25HWB2070\$9.95 box

Hood Hinge Springs

Use these correct tension new springs with your new hood hinges. These springs will properly support your hood.



64-67 Pontiac / Oldsmobile, '71-72 Pontiac w/ Endura Bumper

.....4010-211-64\$16.45 ea

68-72 Pontiac (exc. '71-72 w/ Endura Bumper)

.....4011-211-66\$10.95 ea

Hood Latches

Brand new hood latch assembly replaces worn or broken original. (photo not available)

67 Pontiac4331-319-67\$54.95 ea

78-88 All4145-319-811\$16.45 ea



Radiator Supports



EDP coated steel panels form the inner structure to the front clip. Usually rusted from leaking coolant or collision damage.

66-67 Pontiac (exc. A/C or Ram Air)4331-320-661\$229.95 ea

68-70 Pontiac (exc. '70 Tempest / LeMans) .4333-320-70\$229.95 ea

NOTE: Trim top panel slightly for '68 models, remove bumper hooks for '69 models.

4-2 / GS



Radiator Support Bushings

New bushings replace worn or rotted units that mount the radiator support to the frame of the car. Hardware is included with each kit.

68-72 Pontiac "A" 4332-326-68S \$21.95 kit

ENGINE COMPARTMENT DETAIL

Get the details right, and your engine compartment will be a rare treat for everyone to see at the next car show or cruise-in you attend. Enhance the appearance of the engine and the whole engine bay with correct clips, bolts, screws, straps, brackets, grommets, etc. And what is right at top-dead-center for everyone to see? The air cleaner, of course. Nothing looks better than the original style unit. Today, even many owners of street machines are modifying our stock air cleaners to fit their aftermarket carburetors and fuel injection, for that "period correct" look.



Air Cleaner Lids

New chrome and painted lids used on factory high-performance air cleaners.



67-68 GTO H.O., '66-67 4-4-2 Open Element
 Chrome Lid only 4031-230-667X \$54.95 ea
 69-70 GTO with Ram Air Black Lid only 4020-230-6925 \$32.95 ea

Wiper and Washer Parts

We carry a great selection of parts to get your windshield wipers and windshield washers back in action!



68-72 Wiper Arm / Blade Set, with Hidden Wipers
 4032-242-683S \$131.95 set
 64-67 Wiper Blade (use 2) 4020-242-673P \$21.95 pr
 68-77 Wiper Blade (use 2) 4012-242-683 \$16.45 ea
 78-88 Wiper Blade (use 2) 4021-242-703 \$16.45 ea

Wiper and Washer Parts (continued)



64-66 Pontiac, '66-67 Buick, '70-72 Buick
 Washer Jar (white) 4010-242-641 \$10.95 ea
 Washer Jar Bracket 4010-242-622 \$14.25 ea
 71-72 Pontiac Washer Jar (white) 4012-242-711 \$21.95 ea
 68-69 Oldsmobile Washer Jar (black) 4532-242-681 \$32.95 ea
 70-72 Oldsmobile Washer Jar (white) 4533-242-701 \$32.95 ea



64-83 Washer Jar Cap (w/o lettering) 4010-242-623 \$5.45 ea
 64-70 Washer Jar Cap (w/ lettering) 4010-242-624 \$5.45 ea
 64-88 Washer Jar Filter 4012-242-701 \$3.25 ea
 64-67 Wiper Transmission Linkage Clip HW2413 \$1.05 ea
 HW2414 \$3.25 ea



64-77 Wiper Motor Grommet / Screw Set
 (6 pieces) 4010-242-625S \$14.25 set
 Ground Strap 4010-242-626 \$6.55 ea
 Pump Repair Kit 4010-242-627S \$87.95 kit



Oil Pans

New EDP coated steel stock style oil pan for small block models. Try to find this pan that isn't chrome plated!

78-79 Chevrolet Small-Block V8 (painted) ... 4044-264-651 \$43.95 ea
 (chrome) 4044-264-651C \$54.95 ea
 80-84 Chevrolet Small-Block V8 (painted) ... 4021-264-801 \$43.95 ea
 (chrome) 4021-264-801C \$54.95 ea



Valve Cover Bolt Sets

Complete set of special bolts for Pontiac or Oldsmobile V8 Valve Covers.

64-81 Pontiac V8 (8 pieces) 4330-931-64S \$27.45 set
 64-88 Oldsmobile V8 (18 pieces) 4530-931-64S \$54.95 set



GTO / 4-

Battery Trays and Hardware

New EDP coated steel trays replace a commonly rusted item. Why bother trying to find impossible good used parts or fixing a rusty tray when these are so affordable?



64-67	Pontiac "A" Battery Tray	4330-300-64	\$21.95 ea
68-72	Pontiac "A" Battery Tray	4332-300-68	\$21.95 ea
68-72	Oldsmobile "A" 250 / 350 Battery Tray	4532-300-681	\$32.95 ea
68-72	Oldsmobile "A" 400 / 455 Battery Tray	4532-300-682	\$32.95 ea
68-72	Buick "A" Battery Tray	4432-300-68	\$27.45 ea
78-88	Battery Tray	4035-300-78	\$43.95 ea



68-72	Hold-Down Clamp / Bolt	4031-301-66S	\$6.55 set
78-88	Hold-Down Clamp	4145-301-81	\$7.65 ea

Radiator Caps

Excellent high quality radiator caps for most models. These are highly superior to the cheaper ones on the market.

64-72	All - 15 lb. capacity (RC-15)	4040-306-57	\$43.95 ea
-------	-------------------------------	-------------	------------



Coolant Overflow Jar Caps

Great hard to find replacements for most models equipped with a closed cooling system. This is the cap for the overflow tank.

73-88	Most models	4312-309-73	\$10.95 ea
73-77	Oldsmobile	4512-309-73	\$7.65 ea



Fan Shrouds

Excellent quality reproduction plastic fan shrouds for most popular models.



64-67	Pontiac w/o A/C or HD Cooling	4330-310-641	\$115.45 ea
	w/ A/C or HD Cooling	4330-310-642	\$115.45 ea
69-72	Pontiac V8 (except Grand Prix)	4333-310-70	\$120.95 ea
69-70	Oldsmobile V8	4532-310-69	\$109.95 ea

Radiator Mounting Cushions

Rubber cushions used to mount the radiator to the core support. Use 2 pair per car.

69-77	Pontiac (pair) (use 2)	4332-326-691P	\$16.45 pr
-------	------------------------	---------------	------------



Radiator Support Seals

Rubber strips used to seal the radiator to the radiator support to aid in cooling. (photo not available)

68-72	Oldsmobile "A" with A/C	4532-320-682S	\$21.95 kit
-------	-------------------------	---------------	-------------

Clutch Linkage Parts

All the parts needed to replace the clutch linkage from the pedal pushrod to the clutch fork boot.



64-67	Clutch Pedal Pushrod Seal	4330-951-652	\$16.45 ea
	Clutch Pedal Pushrod Seal Retainer	4031-951-673	\$21.95 ea
68-72	Clutch Pedal Pushrod Seal	4032-951-683	\$16.45 ea
	Clutch Pedal Pushrod Seal Retainer	4032-951-683A	\$21.95 ea
(photo not available)			
64-66	Clutch Pedal Pushrod (straight)	4330-951-651	\$32.95 ea
67	Clutch Pedal Pushrod (1 bend)	4031-951-672	\$32.95 ea



64-67	Countershaft Frame Pivot Bracket	4030-951-646	\$14.25 ea
68-72	Countershaft Frame Pivot Bracket	4032-951-685	\$16.45 ea



65-69	Frame Pivot Ball Stud	4010-951-651	\$13.15 ea
70-77	Frame Pivot Ball Stud	4046-951-694	\$16.45 ea
64-77	Countershaft Pivot Kit (4-pieces)	4041-951-587S	\$7.65 kit
64-77	Countershaft Felt Seals, Pair	4041-951-589P	\$6.55 pr
64-77	Transmission Control Rod Clips, box of 25	HWB2412	\$14.25 box



64-67	Lower Adjustable Pushrod Assembly	4030-951-648S	\$21.95 ea
68-72	Lower Adjustable Pushrod Assembly	4012-951-692S	\$21.95 ea
67-72	Clutch Fork	4020-951-6713	\$54.95 ea
64-77	Clutch Fork Boot	4030-951-6413	\$10.95 ea

FIREWALL AND COWL PARTS



Firewall Parts

All these parts are mounted on the firewall. Use for underhood detailing.



64-81	Power Brake Booster Check Valve (with Grommet)	4000-297-62	\$9.85 ea
64-67	Firewall Wire Harness Gutter (with Screws)	4030-375-643S	\$7.65 ea

-4-2 / GS



Firewall Insulation Pads

New die-cut jute insulation pads for popular models. Each pad comes with late style plastic clips. Correct early style rubber clips can be ordered separately.



- 64-67 Firewall Insulation Pad (w/ plastic clips) 4030-368-64S \$32.95 kit
- 68-72 Firewall Insulation Pad (w/o A/C) 4032-368-681S \$32.95 kit
- (w/ A/C) (w/ plastic clips) 4032-368-682S \$32.95 kit



- 64-70 Firewall Insulation Pad Retainers (set of 4) (rubber style) (use as required) . . . HWB2406 \$16.45 set
- 70-77 Firewall Insulation Pad Retainers, box of 25 (use as required) HWB2405 \$8.75 box

Steering Column Seals and Carpet Guards

Die-cut rubber seals and plastic panels that cover the top edge of the carpet inside.



- 64-67 Steering Column Seal 4030-373-64 \$5.45 ea
- 68-72 Steering Column Seal 4032-373-681 \$7.65 ea
- 64-67 Carpet Guard w/ plastic clips 4030-523-644 \$21.95 ea
- 68-72 Carpet Guard w/ plastic clips 4032-523-685 \$27.45 ea
- 64-69 Carpet Guard Rubber Fastener (use 2) 4043-523-611 \$7.65 ea
- 64-77 Steering Column Coupler Repair Kit . . . 4030-373-641S \$16.45 kit

Toe Boards and Torque Boxes

Steel patch panels for the lower firewall area where it meets the floor pan, and also new firewall to frame torque boxes to repair rusted original parts.



- 64-67 Lower Firewall Repair Patch, 24" W x 17" H, Left / Right 4030-515-64L / R \$54.95 ea
- 68-69 Pontiac Firewall Torque Boxes, pair . . . 4032-370-684P \$142.95 pr

Heater Core Cases and Seals

New steel heater core case, and die-cut seal kits used to seal the heater or A/C system. We even offer the heater delete panels for those not wanting to install a heater.




- 64-77 Heater Core Case (without A/C) 4030-379-641 \$43.95 ea
- Heater Delete Block Off Plates (pair) . . . 4030-374-641S \$197.95 pr
- 64-72 Heater Box Seal Kit (without A/C) 4030-379-642S \$27.45 kit
- 64-67 Heater Box Seal Kit (with A/C) 4030-379-643S \$27.45 kit



- 66-67 Evaporator Core Seal 4031-379-661S \$21.95 ea
- 68-72 Heater Box Seal Kit (with A/C) 4032-379-681S \$27.45 kit

Speedometer Cables and Grommets

New replacement speedometer cables and grommets for use with all popular models. Be sure to measure your original cable carefully to insure compatibility.



- 64-68 Speedometer Cable, 68" long 4030-372-641 \$27.45 ea
- 69-72 Speedometer Cable, 68" long 4032-372-691 \$30.75 ea
- 76.6" long 4032-372-692 \$30.75 ea
- Speedometer Cable Clip 4020-985-69 \$6.55 ea
- 64-72 Speedometer Cable Grommet 4030-985-64 \$7.65 ea

What's that black coating?

It's called EDP, which stands for Electro Deposit Primer, and it makes an excellent primer under your paint job.

As you probably know, factory paint back in the '60's and '70's was usually just sprayed onto the surfaces that could be reached by a spray gun. But this left many blind areas behind braces, etc, completely bare of any paint protection. Hence, many cars rusted within a few years. But EDP coating is applied electrically, almost like a plating process. The excellent rust-resistant coating reaches every nook and cranny, for unparalleled corrosion resistance.

The only surface preparation required is a light scuffing of the surface for better paint adhesion. No stripping is necessary. The panel is protected from rust as long as the EDP coating remains under your paint.

This is one more way that Goodmark® goes the extra mile for our customers!



GTO / 4-

Cowl Parts

New parts used to keep debris out and seal the cowl area.



- 68-72 Lower Cowl Side Panel, Left / Right . . . 4032-385-68L / R . . . \$65.95 ea
- 68-72 Pontiac "A" Cowl Screen Set
without A/C (3 Pieces) 4032-386-681S \$27.45 set
- with A/C (4 Pieces) 4032-386-682S \$27.45 set
- 64-65 Cowl Side Panel to Grille Seals, Pair . . 4030-386-643P \$16.45 pr
- 64-67 Cowl Vent Gaskets, Pair 4030-386-644P \$4.35 pr

Top Dash Panel Patch

EDP coated patch used for the front of the dash panel and the lower windshield channel. This is a common rust area on all GM cars.

- 64-67 57" W x 2" L 4030-521-64 \$65.95 ea
- 68-72 4032-521-68 \$109.95 ea

Body Mount Bushing Sets

New sets of rubber bushings with steel sleeves used to mount the body to the frame of the car. New hardware is included with each kit.



- 64-67 Pontiac "A" Bushing Set (18 bushings plus hardware)
. 4330-990-641S \$98.95 set
- 68-72 Pontiac "A" Bushing Set (bushings plus hardware)
(2-Door, except Convertible) 4332-990-681S \$98.95 set
- (Convertible) 4332-990-682S \$109.95 set



- 64-72 Frame Mount Repair Kit (14 pieces) . . 4030-392-641S \$43.95 kit

DOORS



Door Shells

EDP coated steel door shells for popular models. This is not just the outer skin, but the whole shell.

- 78-81 LeMans / Grand Am Coupe, LH / RH . . 4035-400-78L / R . . \$449.95 ea

Door Skins

EDP coated outer door skins for popular models. This is not the shell, but the outer skin only.



- 68 Pontiac 2-door Hardtop / Convertible,
Left / Right 4332-450-68L / R . . \$296.95 ea
- 69 Pontiac 2-door Hardtop / Convertible,
Left / Right (except Grand Prix) . . . 4332-450-69L / R . . \$296.95 ea



- 78-81 LeMans / Grand Am Coupe, LH / RH . . 4035-450-78L / R . . \$219.95 ea

Door Hinges

We offer new (not rebuilt) hinges to correctly replace your originals. Each hinge is a new casting with new bushings and pins. Lower hinges have the springs and roller assemblies included.



- 64-65 Front Upper (Left = Right) (use 2) . . . 4030-401-641 \$60.45 ea
- 64-65 Front Lower, Left / Right 4030-401-642L / R . . \$60.45 ea
- 66-67 Front Upper (Left = Right) (use 2) . . . 4031-401-661 \$60.45 ea
- 66-67 Front Lower, Left / Right 4031-401-662L / R . . \$60.45 ea



- 68-72 Front Upper (Left = Right) (use 2) . . . 4032-401-681 \$60.45 ea
- 68-72 Front Lower, Left / Right 4032-401-682L / R . . \$65.95 ea


See the **Goodmark** website at www.goodmarkindustries.com for new parts as they are added to our inventory.





Door Hinge Rebuild Kits

We offer new hinge rebuild kits that include all the pins and bushings you need for all 4 door hinges. New hinge bolt sets and lower hinge springs are available separately.



- 64-67 Front Door Rebuild Kit (14 Pieces)4043-402-61S \$16.45 kit
- 68-88 Front Door Rebuild Kit (14 Pieces)4046-402-69S \$16.45 kit
- 64-67 Hinge Bolt Set (24 Pieces)4010-402-64S \$30.75 set
- 68-72 Hinge Bolt Set (30 Pieces)4012-402-68S \$27.45 set



- 64-67 Lower Hinge Spring (use 2)4030-402-641 \$10.95 ea
- 68-72 Lower Hinge Spring (use 2)4012-402-681 \$7.65 ea
- 66-67 Lower Detent Rebuild Kit4031-402-66S \$21.95 kit
- 68-72 Lower Detent Rebuild Kit4032-402-681S \$27.45 kit

Outside Rear View Mirrors

We offer new reproduction die-cast outside rear view mirrors to replace pitted or broken originals. Each mirror comes with the correct mounting kit.



- 64-66 Pontiac "A" (Left = Right)4330-410-64 \$76.95 ea
- 67-68 Pontiac "A" (Left = Right)4331-410-67 \$65.95 ea
- 69-72 Pontiac "A" (Left = Right)4320-410-69 \$65.95 ea
- 68-69 Oldsmobile "A", Left / Right4532-410-68L / R \$87.95 ea
- 70-72 Oldsmobile "A", Left / Right4533-410-70L / R \$87.95 ea
- 67-72 Pontiac "A" Mirror Mount Kit
(Bracket, Gasket and Screw)4011-410-661S \$10.95 kit



- 70-72 Pontiac, '71-72 Olds / Buick Sport Mirrors, LH Remote, RH manual
LH Remote (painted)4021-410-702L \$186.95 ea
- RH Manual (painted)4021-410-702R \$142.95 ea
- LH Bezel (Escutcheon)4021-410-703 \$65.95 ea
- Bezel Retainer4020-410-684 \$21.95 ea
- Mirror Mount Kit, Left / Right4021-410-704LS / RS \$21.95 kit

Vent Window Handles

New die-cast chrome handles for the front door vent windows. Each '64-67 handle comes with the spring washer and roll pin. '68-72 handles come with the retaining clip. Order as required.



- 64-67 (except 66-67 Hardtop / Convertible Models), Left / Right
(includes spring washer and pin)4010-419-62L / R \$27.45 ea
- 66-67 Hardtop / Convertible Handles, Left / Right Pair
(includes spring washers and pins)4031-419-661P \$60.45 pr
- Stud Assembly (use 2)4031-419-661S \$32.95 ea
- Chrome Stud Nut (use 2)4031-419-663 \$8.75 ea
- 68 Black Knob (use 2)4032-419-68 \$16.45 ea
- 69-72 Clear Knob (use 2)4032-419-69 \$16.45 ea



Vent Window Frames

New die-cast chrome frames for the front door vent windows. Commonly pitted or rusted, our excellent quality replacements will dress up your vent windows like they're supposed to be!

- 66-67 Hardtop / Convertible, Left / Right4030-544-661L / R \$120.95 ea



Door Window Regulators

New front door window regulator assembly for models with manual (not power) windows.

- 70-72 2-door Hardtop / Convertible with Manual Windows,
Left / Right4033-420-70L / R \$109.95 ea
- 64-67 Roller and Rivet (use as required)4020-420-673 \$7.65 ea

Window Crank Handles

New die-cast chrome window crank handles for all models. Each handle comes with retaining clip. Use as required, but be sure to order for the entire car so they all match.



- 64 Deluxe (Dual Arm Style)4342-421-59 \$13.15 ea
- 65-66 Chrome Knob4030-421-65 \$13.15 ea
- 67 Black Knob4011-421-67 \$13.15 ea
- 68 Black Knob (closest available)4143-421-69 \$7.65 ea
- Best Quality4143-421-691 \$16.45 ea
- 69-72 Clear Knob (except Grand Prix)4012-421-69 \$7.65 ea
- Best Quality4012-421-691 \$16.45 ea
- 69-72 Grand Prix, '73-76 all (Clear Knob)4020-421-69 \$16.45 ea
- 77-81 Clear Knob4013-421-77 \$7.65 ea
- 82-88 Black Knob4035-421-82 \$7.65 ea



GTO / 4-

Window Crank Handles (continued)



- 64-88 Handle Spring 4042-421-591 \$2.15 ea
- Nylon Washers, Pair 4042-421-592P \$6.55 pr
- Handle Retaining Clips, box of 100 HWB2404 \$5.45 box

Outside Door Handles

We offer complete sets of outside door handles which include both handles, pushbutton assemblies, gaskets, and hardware needed to install on a 2-door model. Some minor trimming of the shaft may be required to match your originals.



- 66-67 2-door Pontiac "A" 4031-440-66S \$54.95 set



- 76-88 2-door, Left / Right (chrome) 4034-440-76L / R ... \$32.95 ea
- 73-88 Handle Nut Kit (4 pieces) 4021-440-701S \$7.65 kit
- Handle Escutcheon (use 2) 4021-440-702 \$10.95 ea
- Handle Latch Rod Clip 4021-440-703 \$1.05 ea

Inside Door Handles

New die-cast chrome handles include retaining clips. Be sure to order enough for the vehicle so they all match.



- 64 Dual Arm Style 4043-441-61 \$13.15 ea
- 64-67 Paddle Style, Left / Right 4042-441-60L / R ... \$19.75 ea
- 65-67 Single Arm Style 4010-441-65 \$13.15 ea
- 68-72 Front, Left / Right 4012-441-68L / R ... \$16.45 ea
- 68-72 Rear 4143-441-68 \$13.15 ea



- 70-72 Grand Prix, Left / Right 4360-441-70L / R ... \$27.45 ea
- 78-88 Left / Right 4035-441-78L / R ... \$13.15 ea

Door Glass Guides


Reproduction parts used to keep the door glass in the correct position.



- 69-72 Door Window Guide Plates, 2-door
Hardtop / Convertible, pair 4032-435-691P \$24.95 pr
- 70-72 Front Door Glass Channel Support, 2-door
Hardtop / Convertible (use 2) 4033-435-702 \$16.95 ea
- Door Glass Window Stopper, 2-door
Hardtop / Convertible (use 2) 4033-435-703 \$16.95 ea
- Door Window Guide Stabilizers, 2-door
Hardtop / Convertible, pair 4033-435-704P \$16.95 pr
- 73-88 Window Rub Block Repair Kit (3 strips for one door)
(cement to OE guide) (use 2) 4034-435-731S \$7.65 kit

Door Latch Remotes

This is the part the inside door handle attaches to, and the linkage rod attaches to it from the latch. Usually worn or broken.



- 66-67 4-Door Hardtop, Left / Right pair 4020-443-671P \$38.45 pr
- 68-72 Left / Right 4020-443-681L / R ... \$16.45 ea
- 64-72 Opening Rod Retaining Clips (pair) ... 4020-443-675P \$10.95 pr
- 64-72 Remote Rod Clip 4041-443-581 \$1.38 ea

Door Latch Assemblies

Forget using that crowbar to get in your ride every time! We offer new latch assemblies that will replace that broken or missing latch and let you enjoy your musclecar the way it was intended. Over Center Springs are also offered separately, which is the most commonly broken part on a latch.



- 64-65 2-Door, Left / Right 4030-444-64L / R .. \$109.95 ea
- 67 All except 4-Door Hardtop, Left / Right 4031-444-671L / R ... \$65.95 ea
- 68 2-Door, Left / Right 4032-444-68L / R ... \$65.95 ea
- 69-70 2-Door, Left / Right 4032-444-69L / R ... \$65.95 ea
- 69-70 4-Door Rear, Left / Right 4012-444-692L / R ... \$65.95 ea
- 71-72 2-Door, Left / Right 4033-444-71L / R ... \$65.95 ea



- 64-72 Latch Over Center Spring, Left / Right 4030-444-641L / R ... \$2.15 ea

Door Lock Knobs & Ferrules

Correct fluted knobs and stainless steel ferrules for the door lock knob. Black knobs can be painted to match other interior colors. Each ferrule contains the correct felt lining and metal tangs. Concoors correct!



- 64-66 .. Knob, Black 4043-491-611 \$4.35 ea
- Knob, Chrome 4043-491-612 \$3.25 ea
- 67 Knobs, Black (pair) 4011-491-671P \$10.95 pr
- Knobs, Chrome (pair) 4011-491-672P \$10.95 pr
- 68 Knobs, Black (pair) 4012-491-68P \$12.05 pr
- 69-70 .. Knobs, Chrome (pair) 4012-491-69P \$10.95 pr
- 71-88 .. Knob, Chrome 4021-491-70 \$10.95 ea



- 68-72 .. Ferrules, Pair 4012-492-68P \$14.25 pr
- 73-76 .. Ferrule 4012-492-68 \$3.25 ea
- 77-88 .. Ferrule 4013-492-77 \$3.25 ea

-4-2 / GS



ROOF AND WINDSHIELD

Windshield Reveal Molding Sets

New stainless steel and anodized aluminum trim for popular models. Each set contains enough moldings to surround the rear window. Clips are available for either front or rear window sets.



- 64-65 .. All, 1966-67 Sedan Front Molding Set (5 pieces)
..... 4030-525-64S..... \$219.95 set
- 66-67 .. Hardtop / Convertible Front Molding Set (5 pieces)
..... 4031-525-66S..... \$219.95 set
- 64-67 .. Front Molding Clip Kit (34 pieces)..... 4030-525-641S..... \$21.95 kit



- 68-72 .. Sedan / Hardtop Front Molding Set (3 pieces)
..... 4032-525-68S..... \$219.95 set
- Lower Molding only (stainless)..... 4032-525-682..... \$164.95 ea
- Molding Clip Kit, Upper and Sides
..... Except Convertible (32 pieces)..... 4032-525-683S..... \$21.95 kit
- Convertible (26 pieces)..... 4032-525-684S..... \$21.95 kit



- 66-67 .. 2-Door Hardtop Rear
..... Molding Set (4 pieces)..... 4031-715-66S..... \$241.95 set
- Molding Clips, box of 50..... HWB2073..... \$16.45 box

Convertible Top Latch Parts

New die-cast and chromed parts to repair original latch assemblies.



- 64-72 .. Latch Hook Knuckle (pin and spring) .. 4030-482-641P..... \$29.65 pr
- Latch Hooks (pair)..... 4030-482-642P..... \$14.25 pr
- 68-72 .. Latch Hook Receptacles, pair..... 4032-482-681P..... \$76.95 pr

Drip Rail Molding Sets

New Anodized aluminum or stainless steel moldings that trim along the roof line and keep rain from running off the roof when your window is cracked open. Complete sets for one car.

- 66-67 .. 2-Door Hardtop (2-pieces)..... 4031-925-66S..... \$76.95 pr



- 68-72 .. Pontiac 2-Door Sedan / Hardtop (6-pieces)
..... (except Grand Prix)..... 4032-925-68S..... \$109.95 set
- 70-72 .. Buick 2-Door Sedan / Hardtop (6-pieces)
..... 4033-925-70S..... \$131.95 set

ROCKERS AND FLOORS



Rocker Panels

New EDP coated panels create the structure under the door. Commonly rusted, and always good to replace.

- 64-67 .. Outer, Left / Right..... 4030-470-64L / R.. \$142.95 ea
- Inner, Left / Right..... 4030-460-64L / R.. \$109.95 ea
- 68-72 .. 2-Door Outer, Left / Right..... 4032-470-68L / R.. \$142.95 ea
- Inner, Left / Right..... 4032-460-68L / R... \$76.95 ea

- 64-67 .. Rocker Panel Drain Flaps (pair)..... 4020-470-672P..... \$6.55 pr

Carpet Sill Plates

New anodized aluminum sill plates trim the edge of the carpet on top of the rocker. Use 2 per car.

- 64-67 .. 2-Door Sill Plates (no emblems) (pair) 4030-575-64C..... \$54.95 pr
- (w/ Fisher Body emblems) (pair)..... 4030-575-64P..... \$76.95 pr
- 68-72 .. 2-Door Sill Plate (no emblem), LH / RH 4032-575-68LC / RC \$27.45 ea
- (w/ Fisher Body emblem), LH / RH. 4032-575-681L / R... \$38.45 ea

- 78-88 .. 2-Door Sill Plate (w/ emblem) (use 2) .. 4035-575-781..... \$54.95 ea

- 64-72 .. Sill Plate Screw Kit (8 Pieces)..... 4030-575-644S..... \$5.45 kit
- Box of 100..... HWB2202..... \$9.85 box



GTO / 4-




Floor Pans


EDP coated floor assemblies and patches help repair even the most rusted out Chevelle. Our full assembly includes the complete floor pan, factory seam to seam, from the firewall to the rear axle kick up, rocker to rocker. All floor braces are included with the floor assembly. Our partial floor pans will cover the entire transmission tunnel when put together for full replacement, and include a few inches up the firewall where it commonly rusts. All floor assemblies and full-length floors ship via Truck Freight.



64-67 .. 1-Piece Full Floor Assembly (includes 3 floor braces)
..... 4030-500-64S..... \$699.95 ea



68-69 .. 2-door 1-Piece Full Floor Assembly
..... (includes 3 floor braces)..... 4032-500-681S.... \$699.95 ea



70-72 .. 2-door 1-Piece Full Floor Assembly
..... (includes 3 floor braces)..... 4033-500-701S.... \$699.95 ea

Floor Pans (continued)



78-88 .. 1-Piece Full Floor Assembly 4035-500-78S..... \$449.95 ea



64-67 .. Full-Length Floor Patches, 30" W x 72" L,
..... Left / Right 4030-500-64L / R.. \$120.95 ea
68-72 .. Full-Length Floor Patches, 30" W x 62" L,
..... Left / Right 4032-500-68L / R.. \$120.95 ea



68-72 .. 1-Piece Full Floor Pan (without braces)
..... (except under rear seat) 4032-500-681..... \$299.95 ea
78-88 .. Full-Length Floor Patches, LH / RH .. 4035-500-78L / R.. \$219.95 ea



Floor Pans (continued)



- 64-67 .. Front Floor Patch, 30" W x 37.5" L,
..... Left / Right 4030-505-64L / R ... \$65.95 ea
- 68-72 .. 2-door Front Floor Patch, 30" W x 32" L,
..... Left / Right 4032-505-68L / R ... \$65.95 ea



- 64-67 .. Rear Floor Patch, 30" W x 34.5" L,
..... Left / Right 4030-510-64L / R ... \$65.95 ea
- 68-72 .. 2-door Rear Floor Patch, 30" W x 30" L,
..... Left / Right 4032-510-68L / R ... \$65.95 ea



- 64-67 .. Under Rear Seat Patch, 30" W x 26" L,
..... Left / Right 4030-511-64L / R ... \$82.45 ea



- 64-67 .. Under Rear Seat Pan, 1-piece 4030-511-64S \$164.95 ea
- 68-72 .. 2-door Under Rear Seat Pan, 1-piece. 4032-511-681S \$120.95 ea



- 73-77 .. 2-door, Front Floor Patch, 31" L 4034-505-73L / R .. \$120.95 ea
- Rear Floor Patch, 26" L 4034-510-73L / R .. \$120.95 ea

Floor Pan Plugs

EDP coated plugs that fit the floor pans and trunk floors. These do not come with our floors, so order if required. 4 are used on the floor pans, and 3 are used on the trunk floor.



- 64-72 .. Oval (EDP) 4030-512-64 \$6.55 ea
- Galvanized 4030-512-64A \$7.65 ea
- 64-67 .. Oval with Notches 4030-512-641 \$6.55 ea
- Galvanized 4030-512-641A \$7.65 ea

Floor Pan Braces

EDP coated steel braces support the floor pans, and are commonly rusted. Seat belt mounting nuts and seat track mounting nuts are welded in place. These are included with our Complete Floor Assembly. Our braces are designed for the later style ('67-up) Seat Belt Bolts with coarse thread.



- 64-69 .. Front Brace 4030-517-641 \$109.95 ea
- 70-72 .. Front Brace 4033-517-701 \$142.95 ea



- 64-69 .. Center Brace 4030-517-642 \$109.95 ea
- 70-72 .. Center Brace 4033-517-702 \$142.95 ea



- 64-67 .. Rear Brace 4030-517-643 \$131.95 ea
- 68-72 .. Rear Brace 4032-517-68 \$131.95 ea

Floor Pan Brackets

EDP coated steel brackets that protect the wiring, support the rear seat divider, and anchor the rear seat to the body.



- 64-65 .. Under Rear Seat Wire Protector 4030-517-644 \$49.45 ea
- 64-67 .. Package Shelf Support Brackets (pair)
..... Welds to under rear seat pan 4030-517-645P \$98.95 pr
- 64-65 .. Rear Seat Anchor Bracket (use 2) 4030-517-646 \$10.95 ea
- 66-72 .. Rear Seat Anchor Bracket (use 2) 4031-517-661 \$14.25 ea
- 64-72 .. Transmission Crossmember Insulators
..... (pair) 4330-517-641P \$21.95 pr

Bucket Seat Mounting Bracket Sets

Complete set of the special brackets welded to the floor for mounting bucket seat tracks. The 2 long brackets support the inner track, and the small brackets welded to the outer front to support the seat track in the front. Excellent for converting to bucket seats!



- 64-65 .. Set of 2 Brackets 4030-507-64P \$54.95 pr
- 66-70 .. Set of 4 Brackets 4031-507-66S \$54.95 set
- 71-72 .. Set of 4 Brackets 4033-507-71S \$54.95 set

M/T Floor Shift "Humps"

Sheetmetal or ABS plastic tunnel that mounts to the floor pan and supports the shifter on floor shift M/T models. Use these when converting to M/T floor shift or replacing floors.



- 64-66 .. Pontiac 4030-507-641 \$54.95 ea
- 70-72 .. Oldsmobile (ABS plastic) 4533-507-701 \$32.95 ea
- 78-80 .. all models (ABS plastic) (can fit '81-88) 4035-507-781 \$32.95 ea



GTO / 4-

Floor Shift Boots and Retainers

Molded rubber boots and die-cast retainers that retain the shift boot to the floor. These are commonly worn or missing when converting to a floor shift stick.



- 64-65 . . Olds w/o console, '64-67 Buick
 - Lower Shift Boot 4030-508-641 \$27.45 ea
 - Shift Boot Retainer 4031-508-672 \$27.45 ea
 - '64-66 Retainer Hardware Kit 4030-508-642S \$5.45 kit
 - '67 Retainer Hardware Kit 4031-508-672S \$6.55 kit
- 65-66 . . Pontiac Upper Shift Boot (with console) 4330-508-653 \$54.95 ea
- 65-67 . . Buick, 68-72 Buick (w/ console) 4430-508-651 \$87.95 ea



- 67-72 . . Pontiac (except '67 w/ console)
 - Shift Boot 4331-508-671 \$27.45 ea
 - Retainer (w/o console) (chrome) 4331-508-672 \$16.45 ea
 - Retainer (w/ console) (black) 4331-508-673 \$14.25 ea
 - Retainer Hardware Kit 4331-508-672S \$5.45 kit
- 68-72 . . Buick (w/o console) 4432-508-681 \$137.45 ea

Park Brake Parts

Brand new parts to repair your park brake system.



- 64-72 . . Equalizer only 4030-519-641 \$7.65 ea
- Connectors only, pair 4030-519-642P \$6.55 pr
- Cable Adjusting Nuts only, pr. 4030-519-643P \$5.45 pr
- Cable Clips only, set of 3 HWB2419 \$8.75 set
- Frame Clips, Box of 25 HWB2416 \$12.05 box
- 68-69 . . Park Brake Handle 4020-519-677 \$9.95 ea

QUARTER PANELS



Factory Style Quarter Panels

New EDP coated factory style quarters feature full coverage to all the factory seams so you can completely replace your quarter panel the way GM intended. No missing door jambs here! All panels ship via Truck Freight.



- 70-72 Cutlass Supreme / 442 Convertible,
 - Left / Right 4560-602-70L / R .. \$549.95 ea

Trunk Weatherstrip Gutters

EDP coated steel gutters welded to the trunk lip opening that form the channel for the trunk weatherstrip. These are not included with a factory quarter panel.



- 64-65 except Wagon (2-Piece Set) 4030-714-64S \$76.95 pr
- 66-67 except Wagon (2-Piece Set) 4031-714-66S \$76.95 pr
- 70-72 Buick "A" except Wagon (2-Piece Set) 4032-714-68S \$76.95 pr

Quarter Skins

EDP coated steel skins are not full panels, but cover from the bottom of the side of the panel up to the beltline. They do not include the sail panel to the roof, the door jamb pillar, nor do they extend to the trunk opening. An excellent choice for repairing rust in the wheel arch or lower rear section. All quarter skins ship via Truck Freight.




- 64-65 Pontiac "A" 2-door, 29" H x 85" L, Left / Right
 - 4330-600-64L / R .. \$252.95 ea
- 66-67 Pontiac "A" 2-door, 30" H x 88" L, Left / Right
 - 4031-600-66L \$230.95 ea

NOTE: This skin is of marginal quality, but is the only panel available.

-4-2 / GS



Quarter Skins (continued)




68 Pontiac "A" 2-door, 33" H x 76" L, Left / Right
 4332-600-68L / R . . \$230.95 ea

69 Pontiac "A" 2-door, 33" H x 76" L, Left / Right
 4332-600-69L / R . . \$230.95 ea



70-72 Pontiac "A" 2-door, 33" H x 78" L, Left / Right
 4333-600-70L / R . . \$230.95 ea

NOTE: This skin is of marginal quality, but is the only panel available.




68-69 Olds "A" 2-door, 28" H x 80" L,
 Left / Right 4532-605-68L / R . . \$252.95 ea

70-72 Olds "A" 2-door (except Supreme), 28" H x 80" L,
 Left / Right 4533-600-70L / R . . \$208.95 ea




70-72 Cutlass Supreme 2-door, 28" H x 80" L,
 Left / Right 4560-600-70L / R . . \$252.95 ea

76-77 Olds "A" 2-door, 30" H x 65" L,
 Left / Right 4534-600-76L / R . . \$230.95 ea



78-80 Cutlass Supreme 2-door, 27" H,
 Left / Right 4562-600-78L / R . . \$329.95 ea

81-88 Cutlass Supreme 2-door, 28" H,
 Left / Right 4562-600-81L / R . . \$230.95 ea



68-69 Buick 2-door, 27" H x 77" L,
 Left / Right 4432-600-68L / R . . \$439.95 ea

NOTE: Modify the side marker hole to be correct for 1968 models.

70-72 Buick 2-door, 28" H x 77" L,
 Left / Right 4433-600-70L / R . . \$219.95 ea

Door Strikers

New Allen head bolt with collar used to screw into the door jamb and strike the door latch. Commonly broken or worn over time.



64-70 Use 2 per car 4030-606-64 \$17.55 ea

70-72 Use 2 per car 4012-606-70 \$Inquire

73-76 Use 2 per car 4047-606-71 \$16.45 ea

78-88 Use 2 per car 4035-606-78 \$10.95 ea

Door Jamb Vent Louvers

New plastic vent louvers found in the door jamb that allow air pressure to escape. Commonly broken or missing the mesh flap and rubber back.



69 2-Door Hardtop / Convertible, pair. . . . 4032-612-69P \$43.95 pr

70-72 2-Door Hardtop / Convertible, pair. . . . 4021-612-70P \$54.95 pr

64-67 Convertible Frame to 1/4 Seals, pair . . . 4030-612-642P \$32.95 pr

68-72 Convertible Frame to 1/4 Seals, pair . . . 4032-612-682P \$65.95 pr

64-65 Quarter Glass "U"-Seals, pair 4030-612-641P \$27.95 pr

66-67 Quarter Glass "U"-Seals, pair 4031-612-661P \$27.95 pr

68-72 Quarter Glass "U"-Seals, pair

(except Tempest / LeMans / GTO) . 4032-612-681P \$27.95 pr

Tempest / LeMans / GTO only 4332-612-68P \$14.95 pr

Rear Wheelhouses

EDP coated steel panels used to form the wheelhouse over the rear wheel. The inner wheelhouse is the one you see inside the trunk. The outer wheelhouse mates up to the quarter panel in the wheel lip. If your quarters are rusty in the wheel opening, you need to replace these, too. These can be modified for convertible models by crushing down the top section to clear the top frame.



64-67 Inner, Left / Right 4030-670-64L / R . . \$164.95 ea

68-72 Inner, Left / Right 4032-670-68L / R . . \$164.95 ea



64-67 Pontiac "A" Outer, Left / Right 4330-675-64L / R . . \$142.95 ea

68-69 Pontiac "A" Outer, Left / Right 4332-675-68L / R . . \$109.95 ea

70-72 Pontiac "A" Outer, Left / Right 4333-675-70L / R . . \$142.95 ea



68-69 Olds "A" Outer, Left / Right 4532-675-68L / R . . \$142.95 ea

70-72 Olds "A" Outer, Left / Right 4533-675-70L / R . . \$142.95 ea



GTO / 4-

Quarter Glass Sash Chrome


This is the vertical chrome molding that holds the weatherstrip between the quarter glass and door glass. Usually pitted from age. Each molding comes with the glass set channel to attach it to the edge of the quarter glass. Weatherstrips are not included, but are available in the weatherstrip section.



- 64-65 2-Door Hardtop, Left / Right 4030-665-641L / R . . \$43.95 ea
- 66-67 2-Door Hardtop / Convertible, Left / Right Pair
 4020-665-67P \$87.95 pr
- 68 2-Door Hardtop / Convertible, Left / Right
 4032-665-68L / R \$43.95 ea
- 69-72 2-Door Hardtop / Convertible, Left / Right Pair
 4032-665-69P \$98.95 pr

Convertible Top Boot Clips

Reproduction sets of new spring steel and plastic clips to mount the top boot on convertible models.



- 64-65 . . Top Boot Clip Set 4030-708-64S \$38.45 kit
- 66-67 . . Top Boot Clip Set (16 pieces) 4031-708-66S \$54.95 kit

Convertible Pinch Weld Molding Clips

Correct reproduction clips used on the moldings that trim the convertible top opening on the tops of the quarters and deck filler.





- 64-65 . . Pinch Weld Molding Clip (as required) . . 4030-711-642 \$4.35 ea
- 66-67 . . Pinch Weld Molding Clip (use 12) 4031-711-662 \$4.35 ea
- 68-72 . . Pinch Weld Molding Clip (as required) . . 4032-711-682 \$4.35 ea

DECK & TRUNK



Trunk Lids

EDP coated steel panels are complete assemblies, not just the outer skin. Bolt-on and paint to match the body. Best quality on the market. All trunk lids are shipped via Truck Freight.

-  
- 70-72 Olds "A" 2-door (except Supreme)
 Trunk Lid 4533-700-70 \$399.95 ea
- 70-72 Cutlass Supreme 2-door Hardtop
 Trunk Lid 4560-700-701 \$399.95 ea
-  
- 70-72 Cutlass Supreme Convertible, all Cutlass 4-door
 Trunk Lid 4560-700-702 \$399.95 ea
- 70-72 Buick "A" Trunk Lid 4032-700-68 \$249.95 ea

Trunk Latches



- Complete latch assembly for popular models. Replaces worn or broken original.
- 64-72 Trunk Latch Assembly 4042-705-59 \$21.95 ea
 - 73-77 Trunk Latch Assembly 4021-705-70 \$54.95 ea
 - 71-72 Trunk Latch Striker 4021-705-703 \$21.95 ea

Rear Spoiler Pads

- Die cut set of rear spoiler pads used on "Judge" rear spoilers. Sold in pairs.
- 69 GTO Judge, pair 4332-701-693P \$5.45 pr

-4-2 / GS



Deck Filler Panels

EDP coated panels that fit between the trunk lid and back window. This is a common rust area on all GM cars.



- 64-65 All 2-Door Sedan / Hardtop 4330-710-64 \$153.95 ea
- 66-67 All 2-Door Sedan / Hardtop 4331-710-66 \$120.95 ea




- 68-72 Pontiac "A" 2-Door Sedan / Hardtop... 4332-710-68 \$120.95 ea
- 69-70 Grand Prix 4032-710-68 \$71.45 ea



- 68-72 All Convertibles 4032-710-682 \$120.95 ea
- 70-72 Cutlass Supreme 2-Door Hardtop 4560-710-70 \$142.95 ea

Trunk Floors

We offer a complete selection of trunk floors for all models. Full trunk floors must be modified to fit along the rear tail panel, but otherwise will completely replace a factory trunk floor. We also offer EDP coated panels to repair rusted trunk floors. Each panel is designed to be able to fit in the trunk opening (so you can replace without removing the body off the frame to install). 7-piece kits include 3 floor sections, 2 floor braces, and 2 body mount braces.



- 64-67 All Full Trunk Floor (modify at tail panel)
..... 4430-725-64S \$599.95 ea



- 68 All Full Trunk Floor (modify at tail panel)
..... 4032-725-681S \$599.95 ea

Trunk Floors (continued)




- 69 Full Factory Trunk Floor (modify at tail panel)
..... 4032-725-69S \$599.95 ea



- 70 Full Factory Trunk Floor (modify at tail panel)
..... 4033-725-70S \$599.95 ea



- 71-72 .. Full Factory Trunk Floor (modify at tail panel)
..... 4033-725-71S \$599.95 ea




- 68-72 .. 1-Piece Center Patch, 56" W x 34" L (Truck Ship)
..... 4032-725-68 \$131.95 ea
- Wagon Tool Well Patch 4032-725-681 \$439.95 ea



GTO / 4-

Trunk Floors (continued)



- 64-67 7-Piece Kit, 67" W x 44" L 4330-725-64S \$296.95 kit
 68-72 7-Piece Kit, 62.5" W x 37" L 4032-725-68S \$296.95 kit



- 73-77 . . . 3-Piece Kit, 61" W x 36" L 4034-725-73S \$362.95 set

Spare Tire Parts


Use these parts to mount the spare tire in the trunk. These items are not included with a new trunk floor, so be sure to order them if needed.



- 64-70 Hold-Down Bracket 4010-726-621 \$7.65 ea
 70-77 Hold-Down Bracket 4021-726-701 \$13.15 ea
 67-81 Spare Tire Bolt and Wing Nut 4011-726-671S \$27.45 set
 64-47 Front Jack Stop Bracket 4030-726-641 \$13.15 ea
 68-72 Front Jack Stop Bracket 4032-726-681 \$13.15 ea

Trunk Floor Drop-Offs

Metal panels that fill between the side of the trunk floor and the lower rear bottom of the quarter panel. These are commonly rusted out, especially when water leaked into the trunk from the back window.



- 64-65 Pontiac, Left / Right 4330-735-64L / R \$98.95 ea
 66-67 Pontiac, Left / Right (modify rear for '67)
 4331-735-66L / R \$98.95 ea



- 68 Pontiac, Left / Right 4332-735-68L / R \$60.45 ea
 69 Pontiac "A", Left / Right 4332-735-69L / R \$Inquire
 70-72 Pontiac "A", Left / Right 4333-735-70L / R \$120.95 ea



- 68-69 Oldsmobile, Left / Right (modify rear for '69)
 4532-735-68L / R \$87.95 ea
 70-72 Oldsmobile, Left / Right 4533-735-70L / R \$87.95 ea
 70-72 Buick, Left / Right 4433-735-70L / R \$87.95 ea

Body Mount Braces

EDP coated braces where the body mount contacts the trunk floor. These are included in our 7-piece trunk floor kits.



- 64-67 Body Mount Brace, Left / Right 4030-740-64L / R \$38.45 ea
 68-72 Body Mount Brace, Left / Right 4032-740-68L / R \$43.95 ea

Trunk Floor Braces

EDP coated braces support the trunk floor. Use 2 per car. These are included in our 7-piece kits. The gas tank strap attaches to this part.



- 64-67 Trunk Floor Brace (use 2) 4330-745-64 \$32.95 ea
 68-72 Trunk Floor Brace (use 2) 4032-745-68 \$43.95 ea



- 64-67 Over Axle Trunk Floor Brace 4030-745-641 \$120.95 ea
 68-69 Over Axle Trunk Floor Brace 4032-745-681 \$120.95 ea
 70 Over Axle Trunk Floor Brace 4033-740-701 \$120.95 ea
 71-72 Over Axle Trunk Floor Brace 4033-740-711 \$120.95 ea

Rear Cross Rails

EDP coated braces weld under the rear of the trunk floor and the rear bumper brackets bolt to this panel. This is a commonly rusted part.



- 64-67 Rear Cross Rail 4030-790-64 \$120.95 ea
 68 Pontiac Rear Cross Rail 4332-790-68 \$Inquire
 69 Pontiac Rear Cross Rail 4332-790-69 \$Inquire



GAS TANKS

Replace rust and muck-filled old gas tanks in your muscle car, with brand new high quality steel Gas Tanks from Goodmark®. There is no cost-efficient way to restore the outside appearance of a gas tank, and the rust particles, sludge, and stale gas residue inside are just carburetor problems waiting to happen. While you're at it, be sure to replace rusted or weakened old straps, brackets, bolts, and gas caps. All Gas Tanks include filler neck unless noted. Some tanks are available set up for EFI with fuel pump and sending unit included.

Gas Tanks



Gas tanks fit all models except Wagon.

- 64 Pontiac "A" (No Vent Pipe) (with filler neck)
(except Wagon) 4330-750-641 \$219.95 ea
(same but set up for EFI) 4330-750-641FI \$769.95 ea
- 65-67 Pontiac "A" (Vent Pipe on Filler Neck) (with filler neck)
(except Wagon) 4330-750-65 \$219.95 ea
(same but set up for EFI) 4331-750-66FI \$769.95 ea
- 64-65 Olds "A", 66 Buick "A" (1 Vent Pipe) (no filler neck)
(except Wagon) 4030-750-64 \$241.95 ea



- 66-67 Olds "A" (2 Rear Vent Pipes) (with filler neck)
(except Wagon) 4531-750-66 \$219.95 ea
(same but set up for EFI) 4531-750-66FI \$769.95 ea
- 64-65 Buick "A" (1 Vent Pipe) (with filler neck)
(except Wagon) 4430-750-64 \$241.95 ea
(same but set up for EFI) 4430-750-64FI \$769.95 ea
- 66-67 Buick "A" (No Vent Pipe) (without filler neck)
(except Wagon) 4330-750-64 \$219.95 ea



- 68 or '70 Pontiac "A" (2 Vent Pipes) (without filler neck)
(except Wagon) (w/o EEC) 4332-750-68 \$208.95 ea
- 69-70 Pontiac "A / G" (1 Vent Pipe) (with filler neck)
(w/o EEC) (except Wagon) 4332-750-69 \$208.95 ea
(same but set up for EFI) 4332-750-69FI \$769.95 ea
- 70 Pontiac "A" (3 Vent Pipes) (with filler neck)
(w/ EEC) (except Wagon) 4333-750-701 \$208.95 ea
(same but set up for EFI) 4333-750-701FI \$769.95 ea

Gas Tanks (continued)



- 71-72 Pontiac "A" (3 Vent Pipes) (with filler neck)
(w/ EEC) 4333-750-71 \$208.95 ea
(same but set up for EFI) 4333-750-71FI \$769.95 ea
- 68-69 Olds / Buick "A" (2 Vent Pipes) (with filler neck)
(except Wagon) 4432-750-68 \$208.95 ea
(same but set up for EFI) 4432-750-68FI \$769.95 ea



- 70 Olds / Buick "A" (with filler neck) (except Wagon)
(w/o EEC) (1 Vent Pipe) 4533-750-701 \$208.95 ea
(w/o EEC) (1 Vent Pipe) (for EFI) 4533-750-701FI \$769.95 ea
(w/o EEC) (2 Vent Pipes) 4533-750-702 \$208.95 ea
(w/o EEC) (2 Vent Pipes) (for EFI) 4533-750-702FI \$769.95 ea
- 70-72 Olds "A" (with filler neck) (except Wagon)
(w/ EEC) (3 Vent Pipes) 4533-750-703 \$230.95 ea
(same but set up for EFI) 4533-750-703FI \$769.95 ea



- 70 Buick "A" (with filler neck) (except Wagon)
(w/ EEC) (3 Vent Pipes) 4033-750-701 \$230.95 ea
(same but set up for EFI) 4433-750-702FI \$769.95 ea
- 71-72 Buick "A" (with filler neck) (w/ EEC)
(except Wagon) (3 Vent Pipes) 4433-750-71 \$208.95 ea
(same but set up for EFI) 4433-750-71FI \$769.95 ea



- 73 Pontiac "A" (except Grand Am), '73 Olds "A" (with filler neck)
(except Wagon) 4034-750-731 \$186.95 ea
- 73 Grand Am / Grand Prix (with filler neck) 4334-750-732 \$263.95 ea
- 74-77 Pontiac "A" (except Grand Am), '76-77 Olds / Buick "A" 2-door
(with filler neck) (except Wagon) 4034-750-74 \$186.95 ea



- 74-75 Grand Am (without filler neck) 4334-750-74 \$186.95 ea
- 74 Grand Prix (with filler neck) 4361-750-74 \$263.95 ea
- 75-77 Grand Prix (with filler neck) 4361-750-75 \$263.95 ea



GTO / 4-

Gas Tanks (continued)




- 73-77 Buick "A" (except '76-77 2-door), '74-77 Olds "A" (except '76-77 2-door) (except Wagon) (with filler neck) 4434-750-73 \$208.95 ea
- 78-87 Pontiac "A / G" (without Diesel) (with filler neck) (except Wagon) 4035-750-781 \$263.95 ea
- 81-84 Pontiac "A / G" (with Diesel) (with filler neck) (except Wagon) 4035-750-811 \$263.95 ea



- 78-83 Wagon (without Diesel) 4035-750-782 \$263.95 ea
- 81-83 Wagon (with Diesel) 4035-750-812 \$263.95 ea
- 78-86 Olds / Buick "A / G" 4-door, 78-80 2-door Fastback (with filler neck) (except Diesel) (except Wagon) 4535-750-78 \$263.95 ea



- 79-85 Olds / Buick "A / G" 4-door, 79-80 2-door Fastback (with filler neck) (with Diesel) (except Wagon) 4535-750-79 \$263.95 ea
- 78-80 Cutlass Supreme Coupe (with filler neck) (except Diesel) 4562-750-78 \$263.95 ea
- (with Diesel) 4562-750-79 \$263.95 ea



- 81-88 Cutlass Supreme Coupe (with filler neck) (except Diesel) 4562-750-811 \$263.95 ea
- (with Diesel) 4562-750-812 \$263.95 ea



- 78-87 Regal Coupe (with filler neck) (without EFI Turbo or Diesel) 4462-750-78 \$263.95 ea
- (with Diesel) 4462-750-81 \$263.95 ea
- (with EFI Turbo) 4462-750-84 \$285.95 ea

Gas Tank Straps

New steel straps that support the gas tank. Sold in matched pairs for one vehicle. Hardware Kits are also available...use if required.



- 64-67 All except Wagon Straps (pair) 4030-749-64P \$54.95 pr
- 64-67 All except Wagon Strap Hardware Kit (4 pieces) 4030-749-641S \$8.75 kit



- 64-67 Wagon Straps (pair) 4080-749-64P \$38.45 pr
- 64-66 Wagon Strap Hardware Kit (18 pieces) 4080-749-641S \$16.45 kit
- 67 Wagon Strap Hardware Kit (24 pieces) 4081-749-671S \$16.45 kit



- 68-72 All except Wagon Straps (pair) 4032-749-68P \$27.45 pr
- 68-72 All except Wagon Strap Hardware Kit (6 pieces) 4032-749-681S \$10.95 kit



- 73-77 All (except Wagon or Grand Am / Grand Prix) Straps (pair) 4034-749-73P \$32.95 pr
- 73-77 Grand Am / Grand Prix Straps (pair) 4334-749-73P \$32.95 pr



- 78-88 All except Wagon Straps (pair) 4035-749-78P \$32.95 pr
- 78-87 Wagon Straps (pair) 4035-749-781P \$38.45 pr

Gas Caps

New caps to replace worn or missing originals. Made by a major OE supplier.






- 64-70 except Wagon 4030-757-641 \$10.95 ea
- 64-70 Wagon (without EEC) 2130-757-621 \$14.25 ea
- 70 Wagon (with EEC) 4012-757-701 \$10.95 ea
- 71-74 All 4012-757-711 \$14.25 ea
- 75-88 All 4013-757-75 \$19.75 ea

-4-2 / GS



Gas Tank Sending Units

Always replace the sending unit when installing a new tank. This insures a good flow of fuel instead of trusting a crudded up rusty pipe to flow fuel to your motor.


- | | | |
|-------|---|-------------------------------|
| |  | |
| 64 | 5/16" pipe without vent tube | 4030-755-641 \$65.95 ea |
| 65-67 | 3/8" pipe without vent tube | 4330-750-651 \$65.95 ea |
| |  | |
| 68-70 | 3/8" pipe without vent tube (w/o wgn) .. | 4032-755-681 \$54.95 ea |
| 68-70 | 3/8" pipe with vent tube (w/o wgn) .. | 4032-755-682 \$54.95 ea |
| 71-72 | 3/8" pipe without vent tube (w/o wgn) .. | 4033-755-711 \$54.95 ea |
| 71-72 | 3/8" pipe with vent tube (w/o wgn) .. | 4033-755-712 \$54.95 ea |
| |  | |
| 73-77 | 5/16" pipe with vent tube (w/o wgn) .. | 4034-755-731 \$98.95 ea |
| 73-77 | 3/8" pipe with 2 vent tubes (w/o wgn) .. | 4034-755-732 \$98.95 ea |
| 78-88 | Gas V8 with 2 outlets (w/o EFI) | 4035-755-781 \$76.95 ea |
| 78-88 | Gas V8 with 3 outlets (w/o EFI) | 4035-755-782 \$76.95 ea |

REAR BODY



Tail Panels


EDP coated steel panel that forms the rear end of the car. The tail lamps usually sit in this panel.

- | | | |
|----|---|-------------------------------|
| |  | |
| 66 | GTO | 4331-850-66 \$384.95 ea |
| 67 | GTO | 4331-850-67 \$362.95 ea |
| 68 | Pontiac | 4332-850-68 \$164.95 ea |

Tail Lamp Parts


New injection molded plastic lenses and sponge gaskets for popular models.

- | | | |
|-------|---|----------------------------------|
| |  | |
| 65 | Pontiac "A" Lens Gaskets (pair) | 4330-845-652P \$14.25 pr |
| 66 | Pontiac "A" Lens Gaskets (pair) | 4331-845-663P \$21.95 pr |
| 67 | Pontiac "A" Lens Gaskets (pair) | 4331-845-673P \$32.95 pr |
| | Tail Lamp Housing Stud / Nut Set
(10 piece set) | 4020-844-693S \$16.45 set |
| |  | |
| 68 | Pontiac "A" Housing to Bumper Seals
(pair) | 4332-843-681P \$10.95 pr |
| 68 | Pontiac "A" Lens Gaskets (pair) | 4332-845-683P \$7.65 pr |
| 69 | Pontiac GTO Lens (use 2) | 4332-845-693 \$142.95 ea |
| 69 | Pontiac GTO Lens Gaskets (pair) | 4332-845-693P \$14.25 pr |
| |  | |
| 70-72 | Pontiac Tempest / LeMans Tail Lamp Housing Shields,
Left / Right pair with clips | 4333-844-703P \$17.55 pr |
| 70-71 | Pontiac GTO Tail Lamp Housing Shields,
Left / Right pair with clips | 4333-844-704P \$17.55 pr |
| |  | |
| 70 | Pontiac LeMans Sport / GTO Tail Lamp Lens,
Left / Right | 4333-845-702L / R .. \$164.95 ea |
| 70-72 | Pontiac "A" Lens Gaskets (pair) | 4333-845-702P \$7.65 pr |
| 71 | Pontiac LeMans Sport / GTO Tail Lamp Lens,
Left / Right | 4333-845-712L / R .. \$164.95 ea |
| 72 | Pontiac GTO Tail Lamp Lens, Left / Right
..... | 4333-845-72L / R .. \$164.95 ea |

- | | | |
|-------|--|-------------------------------|
| |  | |
| 69 | Oldsmobile Tail Lens Gaskets (pair) .. | 4532-845-692P \$5.45 pr |
| 70 | Oldsmobile Tail Lens Gasket (use 4) .. | 4533-845-703 \$14.25 ea |
| 71-72 | Oldsmobile Tail Lens Gasket (use 4) .. | 4533-845-714 \$8.75 ea |
| 68-69 | Buick Tail Lens Gaskets (pair) | 4432-845-682P \$7.65 pr |

Back-Up Lamp Gaskets

New sponge gaskets used between the lens and housing. Sold as pairs.

- | | | |
|-------|--|-------------------------------|
| |  | |
| 64-66 | Pontiac (except Wagon) (pair) | 4330-847-642P \$6.55 pr |
| 67 | Pontiac (except Wagon) (pair) | 4331-847-672P \$6.55 pr |
| 69 | Oldsmobile (except Wagon) (pair) | 4532-847-692P \$5.45 pr |
| 70-72 | Oldsmobile (except Wagon) (pair) | 4533-847-702P \$5.45 pr |



GTO / 4-

Side Markers

New side markers replace broken or missing originals.



- 68-69 Buick / Oldsmobile Front Marker (use 2) \$65.95 ea
.....4532-140-68
- 69 Pontiac Front Markers (pair) \$32.95 pr
.....4320-140-69P
- 68-69 Pontiac (except GTO) Gaskets (pair) \$5.45 pr
.....4332-625-682P
- 69 GTO Gaskets (pair) \$5.45 pr
.....4332-625-692P
- 70-72 Oldsmobile Side Marker Gaskets (4 pieces) \$7.65 set
.....4533-905-703S

EMBLEMS

We have the detail items others don't offer that make the difference between a show car and a nice driver. Our selection of emblems completes your exterior refinishing, and truly makes an old car look brand new. Be sure to research and order all the emblems you need. All emblems are die-cast, chromed and painted where needed, and are licensed reproductions or service GM parts.

Front Bumper Emblems

- 77-79 Pontiac Red Arrowhead \$49.45 ea
.....4321-003-771



Grille Emblems

- 64-66 Pontiac "GTO" \$32.95 ea
.....4330-058-642



Front Fender Emblems

- 64-68 Pontiac GTO (use 2) \$43.95 ea
.....4330-130-642



Door Jamb Stickers

- 67 Aqua "GM" \$6.55 ea
.....4011-453-671
- 68-70 Blue "GM" \$6.55 ea
.....4012-453-681



Quarter Panel Emblems

- 64-67 Pontiac "GTO" (use 2) \$32.95 ea
.....4330-615-644




WEATHERSTRIPS

Detail your car and keep out weather and wind noise with our premium quality rubber Weatherstrips. These excellent reproductions of original parts will help your doors shut with that "new-car" solid sound, and they will keep windows from rattling and scraping against metal door parts. Get new Weatherstrips for your car from Goodmark!

Weatherstrip Kits

Goodmark has all the weatherstripping you need to correctly replace worn originals in one handy kit.



Hardtop Group
Includes: 1) Hood to cowl seal, 2) Door weatherstrips, 3) Quarter glass weatherstrips, 4) Trunk weatherstrips, 5) Roof rail weatherstrips, 6) Lock gaskets.
*No provision of necessary trim and under hood components provided for four door models.

Hardtop Group
Includes: 1) Hood to cowl seal, 2) Door weatherstrips, 3) Quarter glass weatherstrips, 4) Trunk weatherstrips, 5) Roof rail weatherstrips, 6) Lock gaskets.
*No provision of necessary trim and under hood components provided for four door models.

Hardtop Group
Includes: 1) Hood to cowl seal, 2) Door weatherstrips, 3) Quarter glass weatherstrips, 4) Trunk weatherstrips, 5) Roof rail weatherstrips, 6) Lock gaskets.
*No provision of necessary trim and under hood components provided for four door models.

- 64 LeMans / GTO 2-Door Hardtop \$307.95 kit
.....4330-900-645S
- 65 LeMans / GTO 2-Door Hardtop \$307.95 kit
.....4330-900-655S
- 66-67 . . LeMans / GTO 2-Door Hardtop \$307.95 kit
.....4331-900-665S
- 68 LeMans / GTO 2-Door Hardtop \$307.95 kit
.....4332-900-682S
- 69 LeMans / GTO 2-Door Hardtop \$307.95 kit
.....4332-900-692S
- 70-72 . . LeMans / GTO 2-Door Hardtop \$307.95 kit
.....4333-900-702S

NOTE: All Hardtop Kits come with Hood to Cowl Seal, Door Weatherstrips, Roofrail Weatherstrips, Quarter Glass Weatherstrips, Trunk Weatherstrips, Lock Gaskets, and Windowfelts.



Convertible Group
Includes: 1) Hood to cowl seal, 2) Door weatherstrips, 3) Quarter glass weatherstrips, 4) Trunk weatherstrips, 5) Roof rail weatherstrips, 6) Lock gaskets.
*No provision of necessary trim and under hood components provided for four door models.

Convertible Group
Includes: 1) Hood to cowl seal, 2) Door weatherstrips, 3) Quarter glass weatherstrips, 4) Trunk weatherstrips, 5) Roof rail weatherstrips, 6) Lock gaskets.
*No provision of necessary trim and under hood components provided for four door models.

Convertible Group
Includes: 1) Hood to cowl seal, 2) Door weatherstrips, 3) Quarter glass weatherstrips, 4) Trunk weatherstrips, 5) Roof rail weatherstrips, 6) Lock gaskets.
*No provision of necessary trim and under hood components provided for four door models.

- 64 LeMans / GTO 2-Door Convertible \$714.95 kit
.....4330-900-646S
- 65 LeMans / GTO 2-Door Convertible \$714.95 kit
.....4330-900-656S
- 66-67 . . LeMans / GTO 2-Door Convertible \$714.95 kit
.....4331-900-666S
- 68 LeMans / GTO 2-Door Convertible \$714.95 kit
.....4332-900-683S
- 69 LeMans / GTO 2-Door Convertible \$714.95 kit
.....4332-900-693S
- 70-72 . . LeMans / GTO 2-Door Convertible \$714.95 kit
.....4333-900-703S

NOTE: All Convertible Kits come with Hood to Cowl Seal, Door Weatherstrips, Pillar Post Seals, Convertible Top Seals, Quarter Glass Weatherstrips, Door Jamb "U"-Seals, Trunk Weatherstrips, Lock Gaskets, and Windowfelts.




Coupe Group
Includes: 1) Door weatherstrips, 2) Quarter glass weatherstrips, 3) Trunk weatherstrips.
*No provision of necessary trim and under hood components provided for four door models.

- 78-81 . . LeMans / Grand Am 2-Door Coupe \$329.95 kit
.....4035-900-78S
- NOTE:** All Coupe Kits come with Door Weatherstrips, Roofrail Weatherstrips, Trunk Weatherstrip, and Windowfelts.



Weatherstrip Kits (continued)



Hardtop Group
 1) Door weatherstripping
 2) Quarter glass weatherstripping
 3) Door weatherstripping
 4) Door weatherstripping
 5) Door weatherstripping

- 64 F-85 / Cutlass / 442 2-Door Hardtop . . . 4530-900-642S . . . \$329.95 kit
- 65 F-85 / Cutlass / 442 2-Door Hardtop . . . 4530-900-652S . . . \$329.95 kit
- 66-67 . . F-85 / Cutlass / 442 2-Door Hardtop . . . 4531-900-662S . . . \$329.95 kit
- 68 F-85 / Cutlass / 442 2-Door Hardtop . . . 4532-900-682S . . . \$329.95 kit
- 69-72 . . F-85 / Cutlass / 442 2-Door Hardtop . . . 4532-900-692S . . . \$329.95 kit
- 64 Special / Skylark 2-Door Hardtop . . . 4430-900-642S . . . \$329.95 kit
- 65 Special / Skylark / GS 2-Door Hardtop . . 4430-900-652S . . . \$329.95 kit
- 66-67 . . Special / Skylark / GS 2-Door Hardtop . 4431-900-662S . . . \$329.95 kit
- 68 Special / Skylark / GS 2-Door Hardtop . 4432-900-682S . . . \$329.95 kit
- 69 Special / Skylark / GS 2-Door Hardtop . 4432-900-692S . . . \$329.95 kit
- 70-72 . . Skylark / GS 2-Door Hardtop 4433-900-702S . . . \$329.95 kit

NOTE: All Hardtop Kits come with Door Weatherstrips, Roofrail Weatherstrips, Quarter Glass Weatherstrips, Door Jamb "U" Seals, Trunk Weatherstrips, Lock Gaskets, and Windowfelts.



Convertible Group
 1) Door weatherstripping
 2) Quarter glass weatherstripping
 3) Door weatherstripping
 4) Door weatherstripping
 5) Door weatherstripping

- 64 Cutlass / 442 2-Door Convertible 4530-900-643S . . . \$714.95 kit
- 65 Cutlass / 442 2-Door Convertible 4530-900-653S . . . \$714.95 kit
- 66-67 . . Cutlass / 442 2-Door Convertible 4531-900-663S . . . \$714.95 kit
- 68 Cutlass / 442 2-Door Convertible 4532-900-683S . . . \$714.95 kit
- 69-72 . . Cutlass / 442 2-Door Convertible 4532-900-693S . . . \$714.95 kit
- 64 Skylark 2-Door Convertible 4430-900-643S . . . \$714.95 kit
- 65 Skylark / GS 2-Door Convertible 4430-900-653S . . . \$714.95 kit
- 66-67 . . Skylark / GS 2-Door Convertible 4431-900-663S . . . \$714.95 kit
- 68 Skylark / GS 2-Door Convertible 4432-900-683S . . . \$714.95 kit
- 69 Skylark / GS 2-Door Convertible 4432-900-693S . . . \$714.95 kit
- 70-72 . . Skylark / GS 2-Door Convertible 4433-900-703S . . . \$714.95 kit

NOTE: All Convertible Kits come with Door Weatherstrips, Pillar Post Seals, Convertible Top Seals, Quarter Glass Weatherstrips, Door Jamb "U"-Seals, Trunk Weatherstrips, Lock Gaskets, and Windowfelts.



Rubber Bumper Kits

Excellent quality kits include bumpers for hood adjustment, hood to fender, doors, trunk lid, and glovebox.

- 64 Pontiac 4330-904-64S . . . \$16.45 kit
- 65 Pontiac 4330-904-65S . . . \$16.45 kit
- 66-67 . . Pontiac 4331-904-66S . . . \$16.45 kit
- 68-69 . . Pontiac 4332-904-68S . . . \$16.45 kit
- 70 Pontiac 4333-904-70S . . . \$16.45 kit
- 71-72 . . Pontiac 4333-904-71S . . . \$16.45 kit

Hood to Cowl Seals

Seals the hood to the cowl and keeps engine fumes from entering the passenger compartment.

- 64-67 All 4030-280-64 . . . \$14.25 ea
- 68-72 Dense Seal (uses steel clips) 4032-280-681 . . . \$10.95 ea
- Steel Clip Kit 4032-280-681S . . . \$10.95 kit
- Sponge Seal (uses plastic clips) 4032-280-682 . . . \$10.95 ea
- Plastic Clip Kit 4032-280-682S . . . \$5.45 kit

Vent Window Weatherstrips

Weatherstrip that seals the vent window and division post rear glass run channel.



- 64-67 . . Sedan Vent Window (pair) 4030-418-641P . . . \$65.95 pr
- 64-65 . . Hardtop / Convertible Vent Window (pr) 4030-418-642P . . . \$87.95 pr
- Glass Run Channel (pair) 4030-418-644P . . . \$28.55 pr



- 66-67 . . Hardtop / Convertible Vent Window (pr) 4031-418-661P . . . \$87.95 pr
- Glass Run Channel (pair) 4031-418-662P . . . \$28.55 pr
- 68 Sedan Vent Window (pair) 4032-418-681P . . . \$65.95 pr
- Hardtop / Convertible Vent Window (pr) 4032-418-682P . . . \$87.95 pr
- Glass Run Channel (pair) 4032-418-684P . . . \$28.55 pr

Windowfelt Kits

Weatherstrip that seals the glass on the inside and outside of the top edge of the door. Sold in a 4-piece kit for both sides.

(photo not available)

- 78-81 . . LeMans / Grand Am Coupe 4-piece kit 4035-423-78S . . . \$120.95 kit

Window Channel Kits

Weatherstrip that seals around the top and sides of the door glass frame on sedan models.




- 64-67 . . Sedan Kit 4010-431-621S . . . \$27.45 kit
- 68-72 . . Sedan Kit 4012-431-681S . . . \$43.95 kit



GTO / 4-

Windshield Sealing Kits

Seal that fits the front windshield or back glass. Use 1 kit per window. Rubber spacer blocks included.



- 64-88 . . Windshield Seal Kit 4030-535-641S \$21.95 kit
 68-72 . . Glass Stop Clip (use as required) HW2076 \$6.55 ea

Door Weatherstrips

Weatherstrip that wraps around the bottom of the door. Sold in pairs.

- 64-65 2-Door Sedan 4030-425-641P \$76.95 pr
 64-65 2-Door Hardtop / Convertible 4030-425-642P \$76.95 pr
 66-67 2-Door Sedan 4031-425-661P \$76.95 pr
 66-67 2-Door Hardtop / Convertible 4031-425-662P \$76.95 pr
 68-72 2-Door Sedan 4032-425-681P \$76.95 pr
 68 2-Door Hardtop / Convertible (except Pontiac "A")
 4032-425-682P \$76.95 pr
 68 Pontiac "A" 2-Door Hardtop / Convertible
 4332-425-68P \$76.95 pr
 69-72 2-door Hardtop / Convertible (except Pontiac "A"),
 also fits Grand Prix 4032-425-69P \$76.95 pr
 69-72 Pontiac "A" 2-Door Hardtop / Convertible
 4332-425-69P \$76.95 pr
 73-77 2-Door Coupe (except Grand Prix) 4034-425-731P \$87.95 pr
 73-77 Grand Prix 4361-425-73P \$87.95 pr
 78-81 2-Door except '81 Cutlass Supreme / Regal
 4035-425-781P \$87.95 pr
 81-88 Cutlass Supreme / Regal Coupe 4562-425-81P \$87.95 pr

Convertible Pillar Post Weatherstrips

Weatherstrip that seats the vent window from the windshield pillar on convertible models. Sold in pairs.

- 64-65 Pair 4030-536-64P \$76.95 pr
 66-67 Pair 4031-536-66P \$76.95 pr
 68 Pair 4032-536-68P \$76.95 pr
 69-72 Pair 4032-536-69P \$76.95 pr

Hardtop Roofrail Weatherstrips

Weatherstrip that seals the roofrail and windshield pillar from the door and quarter glass. Sold in pairs.

- 64-65 Pair, 2-Door Hardtop 4030-537-64P \$76.95 pr
 66-67 Pair, 2-Door Hardtop 4031-537-661P \$76.95 pr
 68 Pair, 2-Door Hardtop 4032-537-681P \$76.95 pr
 69-72 Pair, 2-Door Hardtop 4032-537-691P \$76.95 pr
 73-77 Pair, 2-Door Coupe (except Grand Prix / Cutlass Supreme / Regal)
 4034-537-731P \$87.95 pr
 73-77 Pair, Grand Prix 4061-537-73P \$87.95 pr
 73-77 Pair, Cutlass Supreme / Salon / Regal 4561-537-73P \$87.95 pr
 78-81 Pair, 2-Door Coupe (except Grand Prix / Cutlass Supreme / Regal)
 4035-537-78P \$87.95 pr
 78-88 Pair, Grand Prix / Cutlass Supreme / Calais / Regal Coupe
 (w/o T-Tops) 4062-537-78P \$87.95 pr
 (w/ T-Tops - on body) 4062-537-781P \$230.95 pr
 (w/ T-Tops - on Tops) 4062-537-782P \$197.95 pr

Quarter Glass Weatherstrips

Weatherstrip that fits in the vertical sash molding on the quarter window and seals the door glass from the quarter glass on 2-door hardtop or convertible models. All our weatherstrips feature steel inserts. Sold in pairs.

- 64-65 Pair, 2-Door Hardtop 4030-664-641P \$21.95 pr
 64-65 Pair, 2-Door Convertible 4030-664-642P \$21.95 pr
 66-67 Pair, 2-Door Hardtop / Convertible 4331-664-66P \$21.95 pr
 68-72 Pair, 2-Door Hardtop / Convertible 4032-664-68P \$21.95 pr

Trunk Weatherstrips

Weatherstrip that seals the trunk opening. Not for Wagon.

- 64-77 4030-703-64 \$10.95 ea
 78-88 4035-703-78 \$27.45 ea



-4-2 / GS



INTERIOR COMPONENTS

Detail the interior of your musclecar, and you'll enjoy driving it more. Nothing is more aggravating than constantly noticing worn, broken, or missing parts right in front of your face, every time you get into your car. Call today, or visit online.

Vent Knobs and Cables and Kick Panels

Parts designed to repair parts located in the kick panels...the knobs and cables for the fresh air cowl vents, and the plastic kick panels themselves.



65-66 . . . with knob and bracket (use 2) 4030-367-653 \$38.45 ea
 Vent Knobs only, box of 12 4010-367-653S \$27.45 box

NOTE: These will fit Pontiac models but knob is incorrect.

67-68 . . . with knob (use 2) 4031-367-673 \$38.45 ea
 Vent Knobs only, pair 4031-367-674P \$21.95 pr



69-72 . . . with knob (12 inch) (with loop end) 4032-367-693 \$38.45 ea
 with knob (14 inch) (with "Z" end) 4032-367-694 \$38.45 ea
 Vent Knobs only, box of 12 4032-367-695S \$32.95 box



64 Kick Panels, with A/C (pair) (black) 4030-408-642P \$87.95 pr
 65-66 . . . Kick Panels, with A/C (pair) (black) 4030-408-652P \$87.95 pr
 67 Kick Panels, with A/C (pair) (black) 4031-408-672P \$87.95 pr
 69-72 . . . Kick Panels, with A/C (pair) (black) 4032-408-693P \$87.95 pr
 64-67 . . . Kick Panel Insulation (pair) 4030-408-643S \$10.95 kit
 68-72 . . . Kick Panel Insulation (pair) 4032-408-683S \$10.95 kit

Door Jamb Windlace

Plastic trim used to cover the pinchweld at the rear door jamb. Typically cracked or worn over the years. May be painted to match other interior colors.



64-67 . . . Sedan / Wagon (pair) (for 2 doors) (black)
 4030-412-641P \$16.45 pr
 Hardtop / Convertible (pair) (black) 4030-412-642P \$16.45 pr

Door Panel Hardware

New parts used to mount interior door panels and pull straps. Use as required.



64-88 . . . Trim Panel Mounting Plug Kit (12 pcs) .4010-453-621S \$10.95 set
 Trim Mount Clip (use as required) 4010-453-622 \$2.15 ea
 73-88 . . . Trim Panel Mount Plastic Clips, box of 50)
 4021-453-701S \$13.15 box



78-85 . . . Door Pull Strap End (use 4) 4321-453-764 \$10.95 ea
 77-85 . . . Door Pull Strap End Cover (use 4) 4321-453-765 \$10.95 ea

Dash Pads

Vinyl wrapped over a urethane molded plastic base for uniform consistency. Available in Black only, paint to match other interior colors.



64 Pontiac Dash Pad, Black 4330-522-641 \$285.95 ea
 65 Pontiac Dash Pad, Black 4330-522-651 \$285.95 ea



66 Pontiac Dash Pad, Black 4331-522-661 \$285.95 ea
 67 Pontiac Dash Pad, Black 4331-522-671 \$285.95 ea



68 Pontiac w/o A/C, Black 4332-522-681 \$362.95 ea
 w/ A/C, Black 4332-522-682 \$362.95 ea

Instrument Cluster Inserts

Laser cut aluminum plates used behind the woodgrain applique on all LeMans and GTO dash panels. Use to mount your new woodgrain inserts.



65 Pontiac 4330-523-651 \$54.95 ea



66 Pontiac w/o A/C 4331-523-662 \$54.95 ea
 w/ A/C 4331-523-663 \$54.95 ea
 67 Pontiac w/o A/C 4331-523-671 \$54.95 ea

Instrument Cluster Applique Kits

Die-cut chrome mylar appliques used to restore original dash panels where the chrome trim has worn off from age. These kits are very accurate and very tough, and are an excellent way to freshen up a dash panel.



69 Pontiac (8-pieces) 4332-523-691AS \$76.95 kit
 70-72 . . . Pontiac (18-pieces) 4333-523-701AS \$93.45 kit



GTO / 4-

Dash Insulation


Die-cut jute insulation used under the dash on popular models.



- 64-67 .. Underdash Insulation Kit 4030-523-6414S \$10.95 kit
- 68-72 .. Underdash Insulation Kit 4032-523-6827S \$16.45 kit

Heater / A/C Parts

Dash vent outlets and assemblies to repair or replace broken, worn, or missing components for your classic musclecar.



- 64-87 .. Pontiac Lap Cooler Deflector (use 2) .. 4330-523-641 \$32.95 ea
- 68 .. Pontiac Dash Vent Outlet (use 2) 4012-523-702 \$21.95 ea
- 66-85 .. Control Panel Knobs, Chrome (4 pcs) 4011-523-6710S \$10.95 set
- Black (4 pcs) 4011-523-6710AS \$10.95 set
- 68-72 .. Oldsmobile w/o A/C Dash Cable
- "AIR" 4532-523-681 \$38.45 ea
- "TEMP" 4532-523-682 \$38.45 ea
- "DEFROST" 4532-523-683 \$38.45 ea
- 64-88 .. All Models Dash Cable Fabrication Kit 4000-523-611S \$219.95 kit



- 68-72 .. All Under Dash Air Door 4032-523-686R \$38.45 ea
- RH Kick Panel Vacuum Pod 4032-523-687R \$43.95 ea
- Cowl Fresh Air Vacuum Pod 4032-523-688 \$43.95 ea

Ignition Switches and Parts

New parts to repair or replace the ignition switch.



- 66-67 Oldsmobile / Buick 4011-523-664 \$32.95 ea
- 68 Oldsmobile 4012-523-683 \$32.95 ea
- 69-88 All w/o Tilt Wheel 4012-523-6914 \$32.95 ea
- 69-88 All w/ Tilt Wheel 4012-523-6915 \$32.95 ea

Headlamp Switches and Parts

Get your headlamps functioning again with our new parts.



- 64-67 All Switch 4010-523-641 \$32.95 ea
- 68-72 All Switch (except '68-69 GTO) 4020-523-6911 \$21.95 ea
- 66-68 Pontiac Switch Nut 4331-523-661 \$14.25 ea
- 69-72 Pontiac Switch Bezel / Retainer 4320-523-698S \$21.95 set

Windshield Wiper Switches and Parts

Restore proper function of your wipers with our new parts.



- 67 All Switch 4011-523-6711 \$43.95 ea
- 64-68 Pontiac Wiper Switch Nut 4342-523-591 \$14.25 ea

Cigarette Lighter Parts

Reproduction parts to correctly replace or repair your Rochester style lighter. These parts do not fit the Casco style lighters used on some models. They are for Rochester style lighters ONLY!



- 69-72 Pontiac Lighter Bezel 4320-523-697 \$14.25 ea
- 67-69 Pontiac Lighter Knob and Element 4320-523-672 \$32.95 ea
- 64-69 All Element only 4010-523-622 \$10.95 ea
- 70-88 All Element only 4012-523-701 \$10.95 ea



- 64-69 All Housing or Case 4010-523-621 \$32.95 ea
- 70-81 All Housing or Case 4012-523-703 \$32.95 ea
- 70-72 Oldsmobile Ashtray Door Spring (use 2) 4533-523-701 \$2.15 ea

Radio Knobs and Nuts

Almost everyone changed the sound system in musclecars over the years... unfortunately for teh restorer they threw out the original radio and knobs! We offer correct replacements to restore your radio like new.



- 67-72 Pontiac Outer Knobs (pair) 4320-523-678P \$21.95 pr
- 67-70 All Radio Shaft Nuts (pair) 4011-523-679P \$6.55 pr



Dome Lamp Lenses and Bases

New plastic bases and lenses to replace broken or missing originals. These are correct replacements.



- 64-67 All Sedan and Pontiac Hardtop
 - Dome Lamp Lens 4330-531-641 \$14.25 ea
 - Dome Lamp Base 4330-531-642 \$16.45 ea
- 64-67 Buick / Oldsmobile Hardtop Sail Panel
 - Lens (use 2) 4043-531-621 \$7.65 ea
 - Base (use 2) 4043-531-622 \$43.95 ea
- 64-72 All Convertible Rear Quarter Panel
 - Lens (use 2) 4010-531-624 \$5.45 ea
 - Base (use 2) 4010-531-625 \$27.45 ea



- 68 All Dome Lamp Assembly 4032-531-683S \$38.45 set
 - Lens only 4032-531-681 \$6.55 ea
 - Base only 4032-531-682 \$21.95 ea
- 69-76 All Dome Lamp (w/o reading lamp)
 - Lens 4320-531-691 \$6.55 ea
 - Base 4320-531-692 \$10.95 ea
- 69 Buick Hardtop Sail Panel
 - Lens (use 2) 4082-531-681 \$5.45 ea
 - Base (use 2) 4082-531-69 \$21.95 ea



- 77-88 All Dome Lamp Lens (w/o reading lamp)
 - 4013-531-771 \$7.65 ea

Headliner and Coat Hook Parts

Headliner moldings, clips, rear window trim moldings, coat hooks, and other parts to trim your headliner.



- 64-67 .. Headliner Front Windlace (black) 4030-533-641 \$16.45 ea
- 68-72 .. Headliner Front Windlace (black) 4032-533-681 \$54.95 ea
- Headliner Rear Windlace (black) 4032-533-682 \$76.95 ea



- 68-72 .. Headliner Bow Clip (center) (use 6) 4012-532-681 \$5.45 ea
- (side) (use as required) 4012-532-682 \$5.45 ea



- 67-70 .. Coat Hooks, Black, pair 4011-532-67P \$16.45 pr
- 71-72 .. Coat Hook, Black (use 2) 4012-532-711 \$7.65 ea
- 73-77 .. Coat Hook, Black (use 2) 4013-532-751 \$10.95 ea
- 73-77 .. Inside Windshield Pillar Molding, L / R . 4034-533-732L / R .. \$38.45 ea

Steering Wheel Parts

We offer a wide selection of steering wheel parts to make your Camaro look like new. These are correct reproductions of hard to find original parts.



- 64-81 .. All Horn Contact / Eyelet / Spring 4030-542-641S \$5.45 kit
- 64-66 .. Pontiac Std. Wheel Horn Cap Mounting Ring
 - 4010-542-624 \$6.55 ea
- 67-68 .. Std. Wheel Horn Cap Mounting Kit 4011-542-671S \$30.75 kit



- 67-77 .. Buick / Oldsmobile Woodgrain / Cushion Grip Steering Wheel
 - Horn Cap Mount / Contact Assembly
 - 4031-542-665 \$21.95 ea
 - Mounting Screw Kit (6 pieces) 4031-542-663S \$8.75 kit



- 67-68 .. Buick / Oldsmobile Woodgrain Steering Wheel
 - Mounting Hub 4011-540-672 \$54.95 ea
 - Wheel Mounting Kit 4011-542-675S \$32.95 kit



- 69-77 .. Buick / Oldsmobile Sport Steering Wheel
 - Mounting Hub 4020-540-693 \$54.95 ea
 - Wheel Mounting Kit (w/o tilt wheel) 4012-542-693S \$38.45 kit
 - Wheel Mounting Kit (w/ tilt wheel) 4012-542-694S \$38.45 kit

Steering Column Parts

Don't forget you need turn signal levers and knobs, and tilt wheel levers and knobs too when restoring your classic. How about the column shift knob? We've got 'em!

(photo not available)

- 67-87 .. Pontiac Tilt Wheel Lever w/ black knob 4331-543-672 \$16.45 ea
- Pontiac Column Shift Knob 4331-543-674 \$14.25 ea



- 67-71 .. Hazard Switch Knob, Chrome 4011-543-677 \$10.95 ea
- 2nd Design, Chrome 4011-543-677A \$10.95 ea



GTO / 4-

Shifters and Shift Knobs

New reproduction parts designed to replace the factory shifter, linkage, or knob on popular models.



- 69-81 . . . Pontiac A/T Floor Shift Knob Button Clip . 4320-552-694 \$4.35 ea
- 68-72 . . . Pontiac A/T Floor Shift Cable Assembly . . 4332-552-682 \$43.95 ea
- 67 Pontiac, 67-68 Oldsmobile TH-400 Shift Cable Bracket
 4020-552-697 \$21.95 ea
- 68-72 . . . Pontiac TH-400 Shift Cable Bracket 4332-552-681 \$38.45 ea

Rear Interior Quarter Trim Panels

Reproduction rear interior side panels that cover the inside of the quarter panel at the bottom.



- 70-72 . . Pontiac "A" / Oldsmobile Cutlass Supreme
 2-door Hardtop Rear Interior Panels,
 Black (4-piece set) 4033-645-701S . . . \$120.95 set

Rear Interior Quarter Ashtrays

Reproduction rear interior ashtrays used with rear amrest bases or trim panels. Be sure to order inserts where required.



- 64-67 . . All except Convertible or 2d Wagon, pair
 (inserts included) 4010-647-622P \$43.95 pr
- 68-69 . . Sedan or Hardtop, w/ ribbed cover 4012-647-68 \$38.45 ea
- Insert (not included with ashtray) 4012-647-682 \$16.45 ea
- 68-69 . . Convertible, w/ ribbed cover 4020-647-671 \$43.95 ea
- Insert (not include with ashtray) 4020-647-672 \$16.45 ea



- 70-72 . . Sedan or Hardtop, w/ smooth cover
 (insert included) 4012-647-70 \$82.45 ea
- Convertible, w/ smooth cover,
 (insert included) 4033-647-70 \$89.95 ea

Trunk Divider Boards and Insulation Kits

This is the panelboard that fits behind the rear seat and keeps noise and smells from the trunk from entering the passenger compartment. Usually rotted from age, always a good idea to replace these items together.



- 64-65 . . Sedan / Hardtop Trunk Divider Panel . . 4030-648-641 \$16.45 ea
- Insulation Kit 4030-649-641 \$14.25 ea
- 66-67 . . Sedan / Hardtop Trunk Divider Panel . . 4031-648-661 \$16.45 ea
- Insulation Kit 4031-649-661 \$14.25 ea
- 68-72 . . Sedan / Hardtop Trunk Divider Panel . . 4032-648-681 \$16.45 ea
- Insulation Kit 4032-649-681 \$14.25 ea

Package Trays and Insulation Kits

This is the panelboard that fits behind the top of the rear seat under the rear window that covers the rear speaker panel. Available in either standard panelboard (w/o rear speaker) or mesh style (w/ rear speaker). Insulation always a good idea to cut down on noise and smells from the trunk (exhaust, etc.) All panels are available in Black only, but may be painted to match other interior colors.



- 66-67 . . 2d Package Tray (std.) 4031-713-663A \$32.95 ea
- 2d Package Tray (mesh) 4031-713-664A \$43.95 ea
- Jute Insulation Kit 4031-713-666 \$10.95 kit

Pedal Pads and Parts

Nothing shows the age of a car than worn, shoddy pedal pads. If you want your car to look like new, you can't leave those old, worn, torn or missing pedal pads in place! We offer correct reproduction parts to replace any part you need.



- 64-67 . . Gas Pedal Ball Stud (use 2) 4043-911-612 \$4.35 ea
- 66-67 . . Pontiac Gas Pedal Pad 4331-911-661 \$21.95 ea
- 66-71 . . Pontiac Gas Pedal Pad Trim 4331-911-662 \$19.75 ea
- 68 Pontiac Gas Pedal Pad 4332-911-681 \$21.95 ea
- 69-71 . . Pontiac Gas Pedal Pad 4332-911-691 \$21.95 ea
- 72-73 . . Pontiac Gas Pedal Pad 4012-911-681 \$7.65 ea
- Gas Pedal Pad Trim 4012-911-682 \$7.65 ea
- 73-77 . . Buick Gas Pedal Pad 4434-911-73 \$22.95 ea
- 78-88 . . Gas Pedal Pad 4035-911-78 \$21.95 ea

- 68-88 . . Gas Pedal Mounting Pin 4012-911-683 \$3.25 ea
- 68-72 . . Gas Pedal Tension Spring 4012-911-684 \$5.45 ea
- 73-77 . . Gas Pedal Tension Spring 4034-911-731 \$1.95 ea
- 78-88 . . Gas Pedal Tension Spring 4012-911-74 \$6.55 ea



- 64-72 . . Buick / Olds M/T Clutch / Brake Pedal Pad (use 2)
 4030-912-64 \$6.55 ea
- 64-71 . . Pontiac M/T Clutch / Brake Pedal Pad (use 2)
 4330-912-641 \$10.95 ea
- Pedal Pad Trim (use 2) 4330-912-642 \$16.45 ea
- 72-77 . . Pontiac M/T Clutch / Brake Pedal Pad (use 2)
 4012-912-681 \$6.55 ea
- Pedal Pad Trim (use 2) 4012-912-683 \$6.55 ea



- 73-77 . . Buick / Oldsmobile Clutch Pedal Pad . . 4047-912-711 \$6.95 ea
- Disc Brake Pedal Pad 4047-912-712 \$6.95 ea
- 78-81 . . M/T Brake / Clutch Pedal Pad (use 2) . . 4035-912-78 \$6.95 ea



Pedal Pads and Parts (continued)



- 64-72 .. Buick / Olds A/T Brake Pedal Pad (no disc logo) 4030-913-64 \$9.85 ea
- 64-71 .. Pontiac A/T Brake Pedal Pad 4330-913-641 \$14.25 ea
- Pedal Pad Trim 4331-913-671 \$14.25 ea
- 72 .. Pontiac A/T Brake Pedal Pad 4020-913-671 \$6.55 ea
- Pedal Pad Trim 4020-913-672 \$6.55 ea
- 78-88 .. A/T Brake Pedal Pad 4035-913-78 \$10.95 ea



- 67-77 .. Buick / Olds, '71-72 Pontiac
..... Park Brake Pedal Pad 4020-914-671 \$6.55 ea
- 64 .. Pontiac Park Brake Pedal Pad 4343-914-63 \$10.95 ea
- 65-70 .. Pontiac Park Brake Pedal Pad 4330-914-651 \$10.95 ea
- Pedal Pad Trim 4330-914-652 \$Inquire
- 78-88 .. Park Brake Pedal Pad 4035-914-78 \$7.65 ea



- 64-77 .. Headlamp Dimmer Switch 4030-915-643 \$21.95 ea
- 64-88 .. Stop Lamp Switch (w/o Cruise Control) 4030-915-642 \$14.25 ea
- 67-88 .. Stop Lamp Switch (w/ Cruise Control) 4031-915-672 \$32.95 ea
- 64-77 .. Stop Lamp Switch Clip HW2411 \$1.38 ea
- 64-88 .. Pedal Pivot Bushings (set of 4) 4010-915-621S \$6.55 set

Seat Parts and Trim

Goodmark offers hard to find parts to help restore your front buckets to factory new condition.



- 64-65 .. Bucket Seat Back Bumpers (set of 4) . 4010-922-621S \$19.75 set
- Bucket Seat End Cap (use 2) 4010-922-622 \$5.45 ea



- 66-72 .. Strato Bucket Seat Parts
- 66-67 .. Headrest Assemblies, Black, pair 4011-921-662P \$219.95 pr
- Headrest Mount Kit (4 pieces) 4011-921-663S \$87.95 set
- 69 .. Headrest Assemblies, Black, pair 4012-921-693P \$219.95 pr
- Headrest Escutcheons, Pair (use 2) ... 4012-921-692P \$38.45 pr

Seat Parts and Trim (continued)



- 70-72 .. Headrest Assemblies, Black, pair 4012-921-702P \$219.95 pr
- Headrest Escutcheons, pair (use 2) . . . 4012-921-701P \$38.45 pr
- 66-72 .. Bucket Seat Back Bumpers / Screws (use 2)
..... 4011-922-662S \$10.95 set



- 66 .. Bucket Seat Back Shells / Side Trim . . 4011-922-663S . . . \$142.95 set
- 67 .. Bucket Seat Back Shells / Side Trim . . 4011-922-673S . . . \$142.95 set



- 68-70 .. Bucket Seat Back Shells / Side Trim . . 4012-922-683S . . . \$142.95 set
- NOTE: These fit 1969-70 models with reclining bucket seats (release on side).*
- 69-72 .. Bucket Seat Back Shells / Side Trim . . 4012-922-693S . . . \$142.95 set



- 67-70 .. Bucket Seat Back Release Knob / Bezel
..... (use 2) (release on side) 4011-922-676 \$38.45 ea
- 69-72 .. Bucket Seat Back Release Button Assembly
..... (use 2) (release on back) 4012-922-691 \$21.95 ea
- 67-70 .. Seat Adjuster Track Knob 4011-922-674 \$6.55 ea
- 67-72 .. Bench Seat Back Release Knob 4011-922-675 \$6.55 ea



- 67-72 .. Bench Seat Hinge Covers, pair 4011-922-671P \$54.95 pr
- Bench Seat Back Stopper Set (4 pcs) . 4011-922-672S \$21.95 set



GTO / 4-

Armrest Bases

New chrome or color-keyed plastic bases for the front door armrests. Pads are not included and not available. Be sure to order the mounting screws if needed.



- 64-67 Short Front Bases, Chrome, Pair4010-923-62P \$32.95 pr
- 64-67 Rear Bases, Left / Right Pair4010-923-621P \$38.45 pr
- 64-67 Base Mounting Screws (4-Piece kit)4010-923-652S \$5.45 kit



- 68-72 Short Black Base, Left / Right4020-923-68L / R \$32.95 ea
- 68-72 Short Red Base, Left / Right4020-923-682L / R \$32.95 ea
- 68-72 Short Medium Blue Base, Left / Right4020-923-686L / R \$32.95 ea
- 68-72 Short Ivy Gold Base, Left / Right4020-923-688L / R \$32.95 ea
- 68-72 Short Pearl Base, Left / Right4020-923-689L / R \$32.95 ea



- 68-72 Short Parchment Base, Left / Right4020-923-681L / R \$32.95 ea
- 69-72 Short Dark Green Base, Left / Right4020-923-684L / R \$32.95 ea
- 68-72 Short Dark Blue Base, Left / Right4020-923-687L / R \$32.95 ea
- 68-72 Short Bright Blue Base, Left / Right4020-923-683L / R \$32.95 ea
- 68-72 Short White Base, Left / Right4020-923-685L / R \$32.95 ea
- 68-72 Short Light Blue Bases, Pair4032-923-681P \$76.95 pr
- 70-71 Short Saddle Bases, Pair4033-923-701P \$76.95 pr
- 70-71 Short Sandalwood Bases, Pair4033-923-702P \$76.95 pr
- 70-72 Short Dark Saddle Bases, Pair4433-923-701P \$76.95 pr



- 68-72 Base Mounting Screw Kit (6-Pieces)4012-923-68S \$7.65 kit
- 68 Short Moldings, Deluxe Model, Pair4020-923-6810P \$43.95 pr
- 68 Short Armrest Baseplates, Pair4032-923-682P \$87.95 pr
- 69-72 Short Armrest Baseplates, Pair4032-923-691P \$65.95 pr

Seat Belt Mounting Bolts and Parts

Brand new bolts to mount your seat belt assemblies. These are almost impossible to find used in good condition...and everyone wants to be safe, right?



- 64-66 . . Front Outer and Single Lap Inner4010-928-621 \$19.75 ea
- Front Inner and Shoulder4010-928-622 \$19.75 ea
- 67-71 . . Front Outer and Single Lap Inner4011-926-671 \$14.25 ea
- Front Inner and Shoulder4011-926-672 \$14.25 ea
- Rear4011-926-673 \$14.25 ea
- 67-68 . . Shoulder Straps (4-pieces)4011-926-674P \$14.25 set
- 69-72 . . Shoulder Straps (4 pieces)4020-926-692P \$14.25 set



- 68-71 . . Shoulder Strap Retainer / Cover Set
- (8 pieces)4012-926-681S \$16.45 set
- Hardware Kit4012-926-682S \$8.75 kit

Inside Rear View Mirrors and Brackets

New inside rear view mirrors with chrome or stainless back. All mirrors feature the day / night flipper and gray vinyl perimeter. Brackets available to mount all mirrors.



- 64-68 . . Day / Night, chrome back
- 8" wide4010-935-623 \$54.95 ea
- 10" wide4012-935-691 \$54.95 ea
- 69-72 . . without Map Lamp, 12" wide4032-935-691 \$54.95 ea
- 64-72 . . Mirror to Bracket Screw4041-936-583 \$5.95 ea



- 64-66 . . All Sedan / Wagon4030-935-641 \$38.45 ea
- 64-66 . . Sport Coupe4031-935-661 \$38.45 ea
- 67 Sport Coupe, with boot4031-935-672 \$54.95 ea
- 68-72 . . 2-door except Convertible or El Camino
- Bracket4012-936-682 \$38.45 ea
- Boot4020-936-683 \$Inquire

Sunvisor Supports and Brackets

Reproduction parts to make the sunvisors swivel and stay up in your car.



- 64-72 . . Support (except convertible) (use 2)4030-941-641 \$32.95 ea
- Mount Screw Kit (4 pieces) (use 2)4030-941-643S \$5.45 kit
- Bushing and Tip Kit (4 pieces)4030-941-644S \$7.65 kit



- 64-65 . . Convertible Support Brackets (pair)4030-941-642P \$87.95 pr
- 66-67 . . Convertible Support Brackets (pair)4031-941-661P \$87.95 pr
- 68-72 . . Convertible Support Brackets (pair)4032-941-681P \$87.95 pr

WHEELS / BRAKES / REAR AXLE

New reproduction parts designed to repair or replace hard to find parts for your wheels, wheel trim, and brake system.



Lug Nuts

Aftermarket bulk lug nuts to replace worn or rusted originals. Everything else on your restoration is new, why not new lug nuts as well?

- 67-81 . . 7/16-20 standard lug nuts, box of 504000-586-1S \$16.45 box
- 64-81 . . Rally Wheel Chrome Capped Lug Nut4312-586-71 \$2.15 ea
- 77-81 . . Pontiac, '78-81 Olds, '80-81 Buick Aluminum Wheel Lug Nut
-4321-586-77 \$7.65 ea

-4-2 / GS



Wheel Trim Rings

New aftermarket sets of wheel trim rings used to trim the optional Rally or Sport Wheels. Sold in sets of 4 for one car.



- 79 14" x 6" Buick Rallye Wheel Trim Rings 4021-587-781S \$98.95 set
- 74-81 . . 14" x 7" Buick Rallye Wheel Trim Rings 4021-587-782S . . . \$109.95 set
- 69-72 . . 14" x 7" Pontiac Rally Wheel, 70-79 Oldsmobile Super Stock II, '72 Buick Rallye Wheel Trim Rings . 4320-587-692S . . . \$109.95 set
- 69-72 . . 15" x 7" Pontiac Rally Wheel, '70-72 Buick Rallye Wheel Trim Rings 4346-587-69S \$142.95 set
- 73-81 . . 15" x 7" Pontiac Rally Wheel Trim Rings 4321-587-772 \$109.95 ea

Wheel Center Caps

New center caps for all popular wheels. Be sure to order enough for all your wheels.



- 70-72 . . Pontiac Rally Wheel Center Cap (use 4) (red center) 4321-588-70 \$142.95 ea
- 73-81 . . Pontiac Rally Wheel Center Cap (use 4) (with arrowhead) 4312-588-731 \$142.95 ea
- 72-76 . . Pontiac Honeycomb Wheel Center Cap (use 4) (with arrowhead) 4321-588-72 \$274.95 ea
- 66-72 . . Oldsmobile Super Stock I Center Cap (use 4) 4531-588-661 \$175.95 ea
- Center Cap Retainer only (use 4) . . 4531-588-662 \$8.75 ea
- 68-74 . . Oldsmobile Super Stock II Center Cap (use 4) 4532-588-68 \$219.95 ea
- 75-79 . . Oldsmobile Super Stock II Center Cap (use 4) 4534-588-751 \$186.95 ea



- 77-87 . . Pontiac Aluminum Wheel Center Cap Insert (use 4) 4334-588-77 \$27.45 ea

Disc Brake Backing Plates

Correctly plated and detailed backing plates for ultimate brake detailing. Plates are sold as matched Left / Right pairs.



- 67-68 . . 4-Piston Calipers, Left / Right Pair . . . 4011-595-67P \$87.95 pr
- 69-70 . . 1-Piston Caliper, 2-Piece Rotor, 4012-595-69P \$87.95 pr
- Left / Right Pair 4012-595-70P \$87.95 pr
- 70-72 . . 1-Piston Caliper, 1-Piece Rotor, 4012-595-70P \$87.95 pr
- Left / Right Pair 4012-595-70P \$87.95 pr

Disc Brake Backing Plates (continued)



- 73-77 . . Disc Brake Backing Plates, LH / RH . . 4021-595-73L / R . . . \$32.95 ea
- 67-69 . . Front Wheel Bearing Caps (pair) 4043-595-611P \$21.95 pr
- 69 Front Caliper Dust Caps (pair) 4012-596-691P \$8.75 pr



Rear Axle Covers

Ever tried finding a 12-bolt rear axle cover that wasn't chrome? Here's a quick way to restore your car's original appearance with the correct cover.

- 70 Pontiac 12-Bolt Rear Axle 4044-860-652 \$54.95 ea
- Rear Axle Vent Tube 4044-860-654 \$6.55 ea

Front Control Arms

New front control arms include new bushings, ball joints, and shafts, ready to install. Lower Control Arms feature "oval style" bushings.



- 64-72 . . Upper Control Arm, Left Right 4030-972-641L / R . . \$120.95 ea
- 64-72 . . Lower Control Arm, Left / Right 4030-973-641L / R . . \$153.95 ea

Rear Control Arms

Brand new rear "boxed" control arms for use with factory sway bars, or for upgrading cars to use factory sway bars without folding from the stress.



- 64-72 . . Lower Control Arm, Boxed, pair 4030-981-642P \$219.95 pr
- 68-72 . . Rear Axle Support Braces, pair (for big block models) 4032-981-681P \$109.95 pr

Rear Coil Spring Insulators

One of the primary sources of rear squeeks and noises is the rear coil springs not being insulated from the body properly. We offer the correct parts to cure this problem.



- 64-66 . . Correct sisal rubber, pair 4030-989-641P \$32.95 pr
- 67-77 . . Rubber, pair 4031-989-671P \$8.75 pr